

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897

Our File No: CS/AIS22005223/VQY3Q2**Date:** 01/09/2022**REFERENCE**

Insured/Claimant:	CHARLES JUNTIRA	Policy No:	SP2000503068	
Date of Loss:	19/05/2022	Nature of Claim:	OD	Claim No: 202222004942/FR

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNB2005Y		
Make & Model:	LAMBORGHINI AVENTADOR LP700-4, 6.5 (A)	Engine No:	L53900858
Reg. Date:	21/02/2012 (Man. Year: 2012)	Chassis No:	ZHWEC1476CLA00558
Colour:	White	Odometer:	26999 km
Engine Capacity:	6498 cc		
Market Value/New Car Price:	S\$572,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	255/30Z R20	Rear Tyre Size:	255/30Z R20
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	104,609.10	102,462.10	2,147.00	2.05
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,300.00	2,840.00	6,460.00	69.46
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	113,909.10	105,302.10	8,607.00	7.56
Approved Total (Overridden) (S\$)		65,000.00		
- Excess (S\$)	15,000.00	15,000.00	0.00	0.00
Nett Amount (S\$)	98,909.10	50,000.00	48,909.10	49.45

INSPECTION

Date of Assignment:	02/06/2022	
Date Inspected:	02/06/2022	Inspected At: Teamwork Garage Pte Ltd (HQ) 53 Ubi Ave 1 #01-24, Paya Ubi Industrial Park Singapore 408934
Estimated Period of Repair:	6.0 days	

Adjuster: Thevan Thomas Karthikesavan**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 31 Aug 2022)
Parts:	M1-COUPE	LAMBORGHINI AVENTADOR LP700-4 6.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNB2005Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER WITH SENSOR HOLE (WCP)	Dented	20,000.00 F	*20,000.00 F
2	4		*FRONT BUMPER PDC SENSOR (WCP)	Cut	1,520.00 F	*1,520.00 F
3	4		*FRONT BUMPER SENSOR BRACKET (WCP)	Bent	340.00 F	*340.00 F
4	2		*FRONT BUMPER RETAINER (WCP)	Necessary	360.00 F	*360.00 F
5	1		*FRONT BUMPER TRIM (COVER) RH (WCP)	Cut	1,500.00 F	*1,500.00 F
6	1		*FRONT BUMPER SPOILER (WCP)	Cut	7,000.00 F	*7,000.00 F
7	1		*FRONT BUMPER DAMPING ELEMENT (FOAM) (WCP)	Cut	1,800.00 F	*1,800.00 F
8	1		*FRONT BUMPER REINFORCEMENT (WCP)	Dented	2,800.00 F	*2,800.00 F
9	1		*FRONT BUMPER MIDDLE LOWER GRILLE (WCP)	Cut	800.00 F	*800.00 F
10	1		*FRONT BUMPER SIDE GRILLE RH (WCP)	Cut	400.00 F	*400.00 F
11	1		*FRONT BUMPER LAMBORGHINI EMBLEM (WCP)	Necessary	750.00 F	*750.00 F
12	1		*FRONT BUMPER UNDER BODY TRIM (WCP)	Cut	2,800.00 F	*2,800.00 F
13	1		*FRONT BUMPER UNDER BODY TRIM RH (WCP)	Cut	2,800.00 F	*2,800.00 F
14	1		*FRONT GRILLE BRACKET HOLDER (WCP)	Dented	1,800.00 F	*1,800.00 F
15	1		*BONNET (WCP)	Dented	16,525.00 F	*16,525.00 F
16	1		*BONNET UPPER CATCH HOOK (WCP)	Serviceable	150.00 F	*- F
17	1		*BONNET LOWER LOCK (WCP)	Serviceable	50.00 F	*- F
18	1		*BONNET RELEASE CABLE (WCP)	Serviceable	220.00 F	*- F
19	2		*BONNET ABSORBER (WCP)	Dented	220.00 F	*220.00 F
20	2		*FRONT HEADLAMP (WCP)	Cracked	16,840.00 F	*16,840.00 F
21	1		*FRONT HEADLAMP CONTROL MODULE RH (WCP)	Serviceable	850.00 F	*- F
22	2		*FRONT HEADLAMP BRACKET (WCP)	Dented	60.00 F	*60.00 F
23	2		*FRONT HEADLAMP SIDE COVER (WCP)	Cut	1,160.00 F	*1,160.00 F
24	1		*FRONT HEADLAMP CONTROL UNIT FOR GAS DISCHARGE (WCP)	Necessary	880.00 F	*880.00 F
25	1		*HEADLAMP POWER MODULE FOR DAY DRIVING LIGHTS (WCP)	Necessary	675.00 F	*675.00 F
26	1		*HEADLAMP INJECTOR UNIT FOR HEADLAMP CLEANING (WCP)	Necessary	260.00 F	*260.00 F
27	1		*HEADLAMP SIDE MARKET SIGNAL LIGHTS (WCP)	Necessary	495.00 F	*495.00 F
28	1		*HEADLAMP BLUB (WCP)	Necessary	1,080.00 F	*1,080.00 F
29	1		*LUGGAGE COMPARTMENT TRIM (WCP)	Cut	2,224.00 F	*2,224.00 F
30	1		*LUGGAGE COMPARTMENT LOCK COVER (WCP)	Cut	103.00 F	*103.00 F
31	1		*LUGGAGE COMPARTMENT SEAL (WCP)	Cut	200.00 F	*200.00 F
32	1		*AIR FILTER BOX (WCP)	Cut	2,600.00 F	*2,600.00 F
33	1		*SIDE COVER RH (WCP)	Cut	103.00 F	*103.00 F
34	1		*FRONT FENDER RH (WCP)	Dented	4,576.00 F	*4,576.00 F
35	1		*FRONT FENDER BRACKET RH (WCP)	Necessary	280.00 F	*280.00 F
36	1		*FRONT FENDER CARRIER RH (WCP)	Necessary	60.00 F	*60.00 F
37	1		*SET FRONT BUMPER CLIP	Necessary	300.00 FS	*50.00 FS
38	1		*SET FRONT GRILLE CLIP	Necessary	300.00 FS	*50.00 FS
39	1		*FRONT NUMBER PLATE	Serviceable	150.00 FS	*- FS
40	1		*SET LUGGAGE COMPARTMENT TRIM CLIP	Necessary	150.00 FS	*50.00 FS

F=Franchise part. S=SpcNett.

Sub Total (\$\$) **95,181.00** **93,161.00**
+ Margin on L,N Items 10.00/10.00% (\$\$) **9,428.10** **9,301.10**

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
					Total Parts (S\$)	104,609.10 102,462.10
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	200.00	50.00
2	TO REPROGRAMME AFTER REPAIR WORKS	New	1,000.00	400.00
3	TO R&R FRONT BUMPER ATTACHMENT	New	350.00	70.00
4	TO R&R BONNET ATTACHMENT	New	350.00	70.00
5	TO REPROGRAMM FRONT HEADLAMP AFTER REPAIR	New	1,000.00	350.00
6	TO MOUNT VEHICLE ON BENCH FOR REPAIR	New	800.00	0.00
7	PANEL BEATING ON AFFECTED AREAS	New	2,800.00	900.00
8	SPRAY PAINTING ON AFFECTED AREAS	New	2,800.00	1,000.00
Gross Labour Cost (\$)			9,300.00	2,840.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >