Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.

> 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807

From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park

Singapore 408933

15 Sep 2022 Attn: Fievel Foo Wenyao Date:

Preliminary Advice

Insured Vehicle No : SLQ2033K

TP Vehicle No : 25/05/2022 : SLV7644M Accident Date Make : TOYOTA VOXY HYBRID Assignment Date : 01/06/2022

Date of Inspection : 01/06/2022 Est. Duration of Repair : 5

Inspection At : JWG INTERNATIONAL PTE LTD (HQ)

BLK 10, ANG MO KIO IND PARK 2A,, #03-08 AMK AUTOPOINT

SINGAPORE 568047

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

| Repairer's Estimate (Gross) | :S\$ | 33,281.67 | |
|-----------------------------|------|-----------|--|
| Revised Amount | :S\$ | 6,901.45 | |
| Check Items (Estimated) | :S\$ | 0.00 | |
| Total | :S\$ | 6,901.45 | |
| | | | |
| Lump Sum Repair | :S\$ | 5,500.00 | |

Total Loss Consideration

| New for Old Value | :S\$ |
|--------------------|------|
| Pre-Accident Value | :S\$ |
| COE / PARF Rebate | :S\$ |
| Salvage Value | :S\$ |
| Margin for Repair | :S\$ |

Remarks

| (|) | The vehicle is economical for repair |
|-----|-----|--|
| (|) | The vehicle is not economical for repair |
| (|) | Part-by-Part repair |
| (X | () | Lump Sum repair |

The above survey was conducted on a 'without prejudice' basis. Please note that the preliminary advice amount (X) (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.