

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22005228/KQY3M4**Date:** 27/07/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00142422101

Claimant Vehicle No : GBG6711G **Insured Vehicle No :** XD1484A

Date of Loss: 30/05/2022 Nature of Claim: TP Claim No: SNM22D203817/C02/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBG6711G**

Make & Model: TOYOTA DYNA 150, 3.0 D 5MT (M) Engine No: 1KD2748149

Reg. Date: 26/09/2017 (Man. Year: 2017) Chassis No: JTFAT35Y50K209080

Colour: Silver Odometer: 139400 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15X8 Rear Tyre Size: 155 R12X8 (D/D)

Front Left Side: OHTSU 8 mm Rear Left Side: Bridgestone 7/7 mm

Front Right Side: OHTSU 8 mm Rear Right Side: Bridgestone 7/7 mm

The above values represent the remaining tyre tread depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|---|-------------------|-------------------|-------------------|---------------|
| Parts | 8,776.82 | 6,020.69 | 2,756.13 | 31.40 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 4,150.00 | 1,940.00 | 2,210.00 | 53.25 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (\$\$) | 12,926.82 | 7,960.69 | 4,966.13 | 38.42 |
| Approved Total (Overridden) (\$\$) | | 6,350.00 | | |
| Nett Amount (\$\$) | 12,926.82 | 6,350.00 | 6,576.82 | 50.88 |

INSPECTION

Date of Assignment: 01/06/2022

Date Inspected: 02/06/2022 Inspected At: Lim Yew Boo Spray Paint Co (HQ)
Blk 10 Sin Ming Industrial Estate, #01-10
Singapore 575645

Estimated Period of Repair: 12.0 days

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

| | | |
|----------------------|--|---|
| Part Source: | (Last Synchronised: 27 Jul 2022) | |
| Parts: | N/A | TOYOTA DYNA 150 3.0 D 5MT (M) (Model not available in database) |
| Labour: | Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for GBG6711G) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|--|-------------|-------------|--------------|
| 1 | 1 | | *REAR TAILGATE | Twisted | 1,565.60 FL | *1,339.25 FL |
| 2 | 4 | | *REAR TAILGATE HINGE | Repair | 742.40 FL | *- FL |
| 3 | 1 | | *REAR TAILGATE SIDE LOCK/LH | Distorted | 220.70 FL | *220.70 FL |
| 4 | 1 | | *REAR TAILGATE SIDE LOCK BRACKET/LH | Repair | 129.10 FL | *- FL |
| 5 | 1 | | *REAR TAILLAMP/LH | Serviceable | 406.20 FL | *- FL |
| 6 | 1 | | *REAR TAILLAMP SIDE BRACKET/LH | Repair | 126.00 FL | *- FL |
| 7 | 1 | | *REAR TAILLAMP SIDE BRACKET RUBBER/LH | Serviceable | 79.90 FL | *- FL |
| 8 | 1 | | *REAR STICKER TOYOTA | Necessary | 253.40 FL | *238.90 FL |
| 9 | 1 | | *REAR STICKER DYNA | Necessary | 110.00 FL | *56.00 FL |
| 10 | 1 | | *REAR 70 KM/H STICKER | Necessary | 15.00 FL | *15.00 FL |
| 11 | 1 | | *REAR 13 PAX STICKER | Necessary | 15.00 FL | *15.00 FL |
| 12 | 1 | | *REAR SIDE GATE/LH | Bent | 1,692.20 FL | *1,409.40 FL |
| 13 | 6 | | *REAR SIDE GATES HINGE/LH | Repair | 1,113.60 FL | *- FL |
| 14 | 1 | | *REAR CANOPY ASSY | Bent | 2,500.00 FS | *2,500.00 FS |
| 15 | 1 | | *REAR CANOPY CANVAS | Torn | 600.00 FS | *350.00 FS |
| 16 | 1 | | *REAR SIDE GATE STAINLESS STEEL RAILING/LH | Bent | 825.00 FS | *700.00 FS |

F=Franchise part. S=SpcNett. L=ListItemDisc.

| | | |
|---|------------------|-----------------|
| Sub Total (S\$) | 10,394.10 | 6,844.25 |
| - List Item Discount on L Items 25.00/25.00% (S\$) | 1,617.28 | 823.56 |
| Total Parts (S\$) | 8,776.82 | 6,020.69 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------------------|--|----------|-----------------|-----------------|
| Labour Items | | | | |
| 1 | TOWING CHARGE | New | 130.00 | 60.00 |
| 2 | TO CHECK ALGNMENT | New | 120.00 | 0.00 |
| 3 | TO CHECK WIRING FUNCTIONS | New | 80.00 | 20.00 |
| 4 | TO APPLY RUST-PROOFING ON REPAIRED/REPLACED PANELS | New | 220.00 | 60.00 |
| 5 | LABOUR CHARGES FOR REMOVE/REFIT, CUTTING/WELDING & REPLACEMENT OF DAMAGES | New | 1,800.00 | 1,000.00 |
| 6 | TO PULL, RESTRAIGHTEN OF THE CHASSIS | New | 600.00 | 0.00 |
| 7 | TO PUTTY,PRIMER & SPRAY PAINT ON LEFT SIDE GATE, REAR TAILGATE, HINGLES, LEFT B AFFECTED PILLAR, LEFT CHASSIS AND AFFECTED LEFT FLATBED USING 2K PAINT | New | 1,200.00 | 800.00 |
| Gross Labour Cost (\$\$) | | | 4,150.00 | 1,940.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >