

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG22005231/VQCE2**Date:** 23/11/2022**REFERENCE**

| | | | | |
|-------------------|---------------|------------------|------------|------------------------|
| Insured/Claimant: | TAN JEE CHING | Policy No: | 2100483963 | |
| Date of Loss: | 22/05/2022 | Nature of Claim: | OD | Claim No: 4095065840SG |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|--|-------------|-------------------|
| Reg No: | SLG8865P | | |
| Make & Model: | AUDI A3, 1.4 SEDAN TFSI (ATTRACTION) (A) | Engine No: | CZC556125 |
| Reg. Date: | 24/09/2016 (Man. Year: 2016) | Chassis No: | WAUZZZ8V5G1099224 |
| Colour: | Black | Odometer: | 72608 km |
| Engine Capacity: | 1395 cc | | |
| Market Value/New Car Price: | S\$69,000.00 | | |
| Sum Insured (S\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|------------------|------------------|------------------|
| Front Tyre Size: | 225/40 R18 | Rear Tyre Size: | 225/40 R18 |
| Front Left Side: | Bridgestone 6 mm | Rear Left Side: | Bridgestone 6 mm |
| Front Right Side: | Bridgestone 6 mm | Rear Right Side: | Bridgestone 6 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|-------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts | 14,532.24 | 3,238.08 | 11,294.16 | 77.72 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 16,122.00 | 3,372.00 | 12,750.00 | 79.08 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 30,654.24 | 6,610.08 | 24,044.16 | 78.44 |
| - Excess (S\$) | 300.00 | 300.00 | 0.00 | 0.00 |
| (S\$) | 30,354.24 | 6,310.08 | 24,044.16 | 79.21 |
| + GST 7.00/7.00% (S\$) | 2,124.80 | 441.71 | 1,683.09 | 79.21 |
| Nett Amount (S\$) | 32,479.04 | 6,751.79 | 25,727.25 | 79.21 |

INSPECTION

| | | |
|-----------------------------|------------|--|
| Date of Assignment: | 01/06/2022 | |
| Date Inspected: | 31/05/2022 | Inspected At: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699 |
| Estimated Period of Repair: | 5.0 days | |

Adjuster: Thevan Thomas Karthikesavan**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|--|---------------|-------------|--------------|
| 1 | 1 | | *REAR BUMPER | Cut | 2,201.00 FS | *1,760.80 FS |
| 2 | 1 | | *REAR BUMPER FIXING PARTS | Serviceable | 201.00 FS | *- FS |
| 3 | 2 | | *REAR BUMPER GUIDE SECTION - LH / RH | Damaged | 36.00 FS | *14.40 FS |
| 4 | 2 | | *REAR BUMPER LOCKING MECHANISM | Not Necessary | 67.00 FS | *- FS |
| 5 | 1 | | *REAR BUMPER SPOILER - LH | Cut | 264.00 FS | *210.80 FS |
| 6 | 1 | | *REAR LIGHT REFLECTOR - RH | Not Necessary | 46.00 FS | *- FS |
| 7 | 1 | | *TAIL LIGHT OUTER - RH | Cracked | 974.00 FS | *778.80 FS |
| 8 | 1 | | *TAIL LIGHT TRIM OUTER - RH | Not Necessary | 34.00 FS | *- FS |
| 9 | 1 | | *TAIL LIGHT INNER - RH | Serviceable | 974.00 FS | *- FS |
| 10 | 1 | | *TAIL LIGHT OUTER - RH | Serviceable | 34.00 FS | *- FS |
| 11 | 1 | | *REAR BUMPER REINFORCEMENT BEAM | Not Necessary | 642.00 FS | *- FS |
| 12 | 2 | | *REAR BUMPER BRACKET - LH / RH | Not Necessary | 30.00 FS | *- FS |
| 13 | 1 | | *REAR BUMPER GUIDE SECTION - RH LOWER | Damaged | 75.00 FS | *59.36 FS |
| 14 | 1 | | *REAR VENT TRIM | Not Necessary | 75.00 FS | *- FS |
| 15 | 2 | | *REAR PARKING AID SENSOR - INNER / OUTER | Cut | 390.24 FS | *390.24 FS |
| 16 | 4 | | *REAR PARKING AID SENSOR SEAL RING | Necessary | 10.00 FS | *8.00 FS |
| 17 | 1 | | *SET REAR BUMPER WIRING | Serviceable | 572.00 FS | *- FS |
| 18 | 1 | | *REAR FENDER - RH | Repair | 4,445.00 FS | *- FS |
| 19 | 1 | | *REAR WINDSCREEN | Serviceable | 905.00 FS | *- FS |
| 20 | 1 | | *QUARTER WINDOW - RH | Serviceable | 635.00 FS | *- FS |
| 21 | 2 | | *PRIMER | Serviceable | 44.00 FS | *- FS |
| 22 | 2 | | *GROMMET | Serviceable | 38.00 FS | *- FS |
| 23 | 1 | | *FUEL INSERT | Serviceable | 100.00 FS | *- FS |
| 24 | 1 | | *REAR WHEEL HOUSING LINER - RH | Serviceable | 260.00 FS | *- FS |
| 25 | 1 | | *ACRYLIC SEALANT | Serviceable | 180.00 FS | *- FS |
| 26 | 1 | | *CAVITY WAX | Serviceable | 140.00 FS | *- FS |
| 27 | 1 | | *STONE CHIP | Serviceable | 180.00 FS | *- FS |
| 28 | 1 | | *METAL FILLER POWDER | Serviceable | 280.00 FS | *- FS |
| 29 | 1 | | *REAR WINDSCREEN SEALANT | Serviceable | 200.00 FS | *- FS |
| 30 | 1 | | *1/4 GLASS SEALANT | Serviceable | 100.00 FS | *- FS |
| 31 | 1 | | *SUNDRIES | Necessary | 400.00 FS | *15.68 FS |

F=Franchise part. S=SpcNett.

| | | |
|---------------------------|------------------|-----------------|
| Total Parts (\$\$) | 14,532.24 | 3,238.08 |
|---------------------------|------------------|-----------------|

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------------------|---|----------|------------------|-----------------|
| Labour Items | | | | |
| 1 | TO REMOVE AND TRANSFER REAR PARKING AID | New | 280.00 | 280.00 |
| 2 | TO RENEW REAR WINDSCREEN AND RHS 1/4 GLASS TO FACILITATE RENEWAL OF BOTH REAR FENDERS | New | 600.00 | 0.00 |
| 3 | TO CARRY OUT WATER SEEPAGE FOR REAR WINDSCREEN | New | 200.00 | 0.00 |
| 4 | TO INSTALL SOLAR FILM FOR REAR WINDSCREEN AND RHS 1/4 GLASS | New | 400.00 | 0.00 |
| 5 | TO DISLodge AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY | New | 1,400.00 | 0.00 |
| 6 | TO DISMANTLE AND RENEW REAR BUMPER. TO CUT OUT AND WELD RHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED | New | 4,900.00 | 1,000.00 |
| 7 | TO CARRY OUT DIAGNOSTIC CHECK | New | 192.00 | 192.00 |
| 8 | TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, CD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLodge ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC | New | 1,400.00 | 0.00 |
| 9 | TO RESPRAY REAR BUMPER, RHS REAR FENDER, RHS SILL PANEL, ROOF CHANNEL, DOOR CHANNEL, DOOR ENTRANCE AND REAR END PANELLING | New | 5,000.00 | 1,100.00 |
| 10 | TO REPAIR RHS TAILLAMP PANEL (Supplementary) | New | 700.00 | 250.00 |
| 11 | TO RESPRAY RHS TAILLAMP PANEL (Supplementary) | New | 1,050.00 | 550.00 |
| Gross Labour Cost (\$\$) | | | 16,122.00 | 3,372.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >