



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKK 1357B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	MLDG,F/DR WDO BELT LINE,LH (SN)	CUT	89.00	89.00
1	GLASS,FR DOOR WINDOW,LH (SN)	CUT	398.00	398.00
1	MIRROR ASSY,DOOR,LH (SN)	BROKEN	824.00	824.00
1	COVER,DOOR MIRROR,OTR LH (SN)	CUT	101.00	101.00
1	SUNDRIES (SN)	NECESSARY	30.00	20.00
			1,442.00	1,432.00
	<u>LABOUR</u>			
	REPLACE LH WING MIRROR ASSY		1,280.00	640.00
	REPAIR ON FRT LH FENDER & FRT LH DOOR PANEL.			
	PAINT WORK ON FRT LH FENDER, FRT LH DOOR & LH WING MIRROR COVER.		1,650.00	650.00
	REPLACE FRT LH WINDOW GLASS.		250.00	150.00
	PERFORM RUST PREVENTION.	NOT NECESSARY	50.00	-
	TO APPLY SEALANT ON AFFECTED AREA.	NOT NECESSARY	50.00	-
	TO SUPPLY WINDOW GLASS SOLAR FILM.		180.00	180.00
	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM.		120.00	120.00
	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM.		280.00	280.00
			3,860.00	2,020.00
	GRAND TOTAL		5,302.00	3,452.00
	RECOMMENDED COST OF REPAIRS			3,452.00

Report Ref No. CS/FCI22005232/Eqy3m4

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.