

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIS22005237/UVY3E2

Date: 23/06/2022

REFERENCE

Handling Insurer: Allianz Insurance Singapore Pte. Ltd. Policy No: SP2000434557
Claimant Vehicle No : FBP5309U **Insured Vehicle No :** SLE9024D
Date of Loss: 10/05/2022 Nature of Claim: TP Claim No: 202222004832GK-FR

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBP5309U**
Make & Model: YAMAHA AEROX 155A, 155cc Engine No: G3J8E0098083
Reg. Date: 17/04/2019 (Man. Year: 2019) Chassis No: MH3SG4640KJ053309
Colour: Grey Odometer: 119898 km
Engine Capacity: 155 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 120/70-14 Rear Tyre Size: 140/70-14
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,036.00	6,537.40	7,498.60	53.42
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,430.00	980.00	450.00	31.47
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,466.00	7,517.40	7,948.60	51.39
Approved Total (Overridden) (S\$)		6,000.00		
(S\$)	15,466.00	6,000.00	9,466.00	61.21
+ GST 7.00/7.00% (S\$)	1,082.62	420.00	662.62	61.21
Nett Amount (S\$)	16,548.62	6,420.00	10,128.62	61.21

INSPECTION

Date of Assignment: 02/06/2022
Date Inspected: 02/06/2022 Inspected At: Fastech Auto Pte Ltd (HQ)
1 Kaki Bukit Ave 6, #01-46/48/50 Autobay
Singapore 417883
Estimated Period of Repair: 6.0 days

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 23 Jun 2022)	
Parts:	N/A	YAMAHA AEROX 155A 155cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBP5309U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEADLAMP	Cracked	545.00 F	*499.00 FL
2	1		*FRONT COVER	Cracked	199.00 F	*155.00 FL
3	1		*FRONT COVER PANEL TOP	Not Necessary	85.00 F	*- FL
4	2		*FRT COVER FARING OUTERS	Cracked	410.00 F	*320.00 FL
5	2		*FRT COVER FARING INNERS	Cracked	210.00 F	*300.00 FL
6	2		*MIRRORS	Damaged	136.00 F	*136.00 FL
7	1		*FRONT FENDER UPPER	Cracked	98.00 F	*98.00 FL
8	1		*FRONT FENDER LOWER	No such part	85.00 F	*- FL
9	1		*SET FRONT FORKS ASSY	Bent / Twisted	1,500.00 F	*798.00 FL
10	1		*FRONT FORK BRACKET	Bent	225.00 F	*198.00 FL
11	1		*FRONT WHEEL	Repair	545.00 F	*- FL
12	1		*FRONT BRAKE DISC	Warped	180.00 F	*160.00 FL
13	1		*FRONT CALIPER ASSY	Serviceable	480.00 F	*- FL
14	1		*FRONT UNDER COVER	Torn	165.00 F	*142.00 FL
15	1		*FRONT SIGNAL LAMPS	O/S Cracked	170.00 F	*85.00 FL
16	1		*HANDLE BAR	Bent	192.00 F	*175.00 FL
17	2		*BALANCERS	Cut	50.00 F	*50.00 FL
18	2		*HANDLE GRIPS	Not Necessary	120.00 F	*- FL
19	2		*BRAKE LEVER	Cut	180.00 F	*120.00 FL
20	1		*MASTER PUMP	Not Necessary	195.00 F	*- FL
21	1		*METER PANEL COVER	Cracked	82.00 F	*82.00 FL
22	2		*FOOTSTEP UPPER COVERS	Cut	360.00 F	*290.00 FL
23	2		*FOOTSTEP UPPER GARNISHES	Cut	332.00 F	*310.00 FL
24	2		*FOOTSTEP LOWER GARNISHS	Cut	300.00 F	*260.00 FL
25	1		*SIDE STAND	Bent / Cut	80.00 F	*80.00 FL
26	1		*MAIN STAND	Twisted	190.00 F	*165.00 FL
27	1		*REAR FOOT RESTS	N/S Cut	170.00 F	*58.00 FL
28	1		*REAR EXHAUST GARNISH	Distorted	122.00 F	*102.00 FL
29	1		*REAR EXHAUST	Dented	555.00 F	*535.00 FL
30	1		*RADIATOR OUTER GARNISH	Cut	68.00 F	*68.00 FL
31	1		*RADIATOR	Punctured	550.00 F	*405.00 FL
32	1		*AIR BOX COVER	Cut	185.00 F	*165.00 FL
33	1		*BELT BOX COVER	Cut	182.00 F	*180.00 FL
34	2		*SIDE BOX COVERS	Cracked	450.00 F	*360.00 FL
35	2		*SIDE BOX LOWER COVERS	Cracked	380.00 F	*380.00 FL
36	1		*COMPARTMENT COVER	Cracked	900.00 F	*350.00 FL
37	1		*ABS PUMP	Serviceable	1,800.00 F	*- FL
38	1		*REAR SIGNAL LAMPS	N/S Cut / O/S NotNecessary	170.00 F	*60.00 FL
39	1		*TAIL COVER	Not Necessary	280.00 F	*- FL
40	1		*REAR LICENCE PLATE	Not Necessary	10.00 FS	*- FS
41	1		*FRONT LICENCE PLATE	Not Necessary	10.00 FS	*- FS
42	1		*REAR TOP BOX	Not fitted	380.00 FS	*- FS
43	1		*SET REAR TOP BOX RACK	Not fitted	250.00 FS	*- FS
44	1		*SET BODY STICKER	Necessary	100.00 FS	*60.00 FS
45	1		*SET SIDE BOX COVER EMBLEM	Necessary	100.00 FS	*50.00 FS
46	1		*IU UNIT ASSY	Serviceable	175.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*HAND PHONE HOLDER	Damaged	85.00 FS	*50.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					14,036.00	7,246.00
- List Item Discount on L Items 0.00/10.00% (S\$)					0.00	708.60
Total Parts (S\$)					14,036.00	6,537.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO STRAIGHTEN BODY ALIGNMENT	New	380.00	300.00
2	LABOUR CHARGE	New	550.00	380.00
3	TO PUTTY & SPRAY PAINTING	New	500.00	300.00
Gross Labour Cost (S\$)			1,430.00	980.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >