



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMQ 500E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER FASCIA	DENTED / DEFORMED	2,295.00	2,295.00
1	SET REAR BUMPER CLIPS	NECESSARY	100.00	100.00
2	REAR BUMPER SIDE RETAINER L&R @\$56.00	NOT NECESSARY	112.00	-
1	REAR BUMPER SENSOR (CENTRE)	NOT NECESSARY	195.00	-
1	REAR BUMPER DIFFUSER	CUT	630.00	630.00
1	REAR BUMPER CHROME CENTRE	NOT NECESSARY	138.00	-
2	REAR BUMPER CHROME L&R @\$195.00	NOT NECESSARY	390.00	-
	LESS 10% DISCOUNT		-	-302.50
			3,860.00	2,722.50
	<u>LABOUR</u>			
	CUT OUT, RENEW, KNOCKING & WELDING REAR END PANEL, REMOVE & INSTALL ALL DAMAGE PARTS, STRAIGHTEN & RE-ALIGN BODY.		780.00	300.00
	SPRAY PAINTING ON DAMAGE PARTS.		680.00	400.00
	REMOVE & REFIX REAR BUMPER SENSOR.}		100.00	60.00
	CHECK ALL LIGHTING AFTER REPAIRS.}		45.00	-
			1,605.00	760.00
GRAND TOTAL			5,465.00	3,482.50
RECOMMENDED COST OF REPAIRS				3,482.50

Report Ref No. CS/UOI22005241/Uvy3m4

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.