11/3/22, 2:12 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22005242/AVY3Q2

Date: 03/11/2022

REFERENCE

Handling Insurer: China Taiping Insurance

(Singapore) Pte. Ltd.

Policy No: DMPCSNA00047662204

Claimant Vehicle

SLG9669H

Insured Vehicle No :

SLT3168H

No:
Date of Loss:

30/05/2022

Nature of Claim: TP

Claim

SNM22D203827/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLG9669H

 Make & Model:
 HONDA VEZEL, 1.5 (A)
 Engine No:
 L15Z1003206

 Reg. Date:
 27/01/2022 (Man. Year: 2021)
 Chassis No:
 RV31002626

 Colour:
 White
 Odometer:
 7720 km

Engine Capacity: 1496 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16
Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm
Front Right Side: Dunlop 6 mm
Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,952.00	1,062.00	890.00	45.59
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,350.00	630.00	720.00	53.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,302.00	1,692.00	1,610.00	48.76
+ GST 7.00/7.00% (S\$)	231.14	118.44	112.70	48.76
Nett Amount (S\$)	3,533.14	1,810.44	1,722.70	48.76

INSPECTION

Date Inspected:

Date of Assignment: 02/06/2022

BLK 3007 UBI ROAD 1 #01-450

04/07/2022 Inspected At: SINGPORE 408700

Repairer: Jack Cars Enterprise Pte Ltd (HQ)

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 02 Nov 2022)

Parts: M1-SUV HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLG9669H)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FOG LAMP COVER (LEFT)	Not Necessary	220.00 FL	*- FL
2	1		*WHEEL ARCH -FRONT LEFT	Cut	180.00 FL	*180.00 FL
3	1		*FRONT BUMPER	Deformed	980.00 FL	*880.00 FL
4	1		*FRONT BUMPER LOWER LIPS	Cut	230.00 FL	*230.00 FL
5	1		*FRONT BUMPER BRACKET	Not Necessary	80.00 FL	*-FL
6	1		*FRONT FENDER -LEFT (NPA)	Repair	0.00 FL	*- FL
7	1		*RIM -FRONT LEFT	Not Necessary	500.00 FS	*-FS
8	1		*CLIPS ,SCREW & RIVETS	Necessary	100.00 FS	*30.00 FS
F=Fra	anchise	part. S=SpcNe	tt. L=ListItemDisc.			
				Sub Total (S\$)	2,290.00	1,320.00
			- List Item Discount	on L Items 20.00/20.00% (S\$)	338.00	258.00
				Total Parts (S\$)	1,952.00	1,062.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO PUTTY & SPRAY PAINT OF AFFECTED AREA	New	700.00	400.00
2	TO PANEL BEAT & TO REMOVE DAMAGED & NECESSARY PARTS & ATTACHMENTS KNOCK ,JACK ,WELD ,RESHAPE AND ALIGN ALL AFFECTED PORTIONS	New	500.00	200.00
3	TO CHECK LIGHTING SYSTEM ,WIRING & REWIRE	New	150.00	30.00
	Gross Labour Cost (S\$)		1,350.00	630.00
	Report was unsubmitted during this	print-out.		

< END OF ESTIMATES >