



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 5717H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	HEADLAMP RH	NOT NECESSARY	2,735.28	-
1	FRONT BUMPER COVER	CUT	586.18	586.18
1	FRONT BUMPER SIDE BRACKET RH	NOT NECESSARY	90.75	-
10	FRONT BUMPER CLIPS	NECESSARY	22.00	22.00
1	FRT FENDER HYBRID EMBLEM RH	NECESSARY	86.50	86.50
1	FRONT FENDER SUB ASSY RH	TO REPAIR SEE LABOUR	1,111.93	-
1	FRONT BUMPER SIDE RETAINER RH	NOT NECESSARY	77.00	-
1	FRT WHEEL RIM RH	TO REPAIR SEE LABOUR	1,570.55	-
1	FRT BUMPER SIDE GRILLE RH	CUT	85.10	85.10
	LESS 25% DISCOUNT		-1,591.32	-194.95
			4,773.97	584.83
<b>SPECIAL NETT ITEMS</b>				
1	FRT FENDER ADVERTISEMENT STICKER RH (SN)	CUT	100.00	100.00
			100.00	100.00
<b>LABOUR</b>				
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF FRONT FENDER SUB ASSY RH AND FRT WHEEL RIM RH.		750.00	350.00
	SPRAY PAINTING CHARGE.		750.00	500.00
	TUFF KOTE.	NOT NECESSARY	60.00	-
	CHECK ALL LIGHTING.	NOT NECESSARY	60.00	-
			1,620.00	850.00
<b>GRAND TOTAL</b>			<b>6,493.97</b>	<b>1,534.83</b>

<b>RECOMMENDED COST OF REPAIRS (CONFIRMED)</b>			<b>1,534.83</b>
--	--	--	-----------------

Report Ref No. NS/INC22005263/Gqce2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.