

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT CS3/ASM22005271/Vvcm4 AXA INSURANCE PTE LTD Ref: 8 SHENTON WAY #24-01 AXA TOWER Date: 22/08/2022 SINGAPORE 068811 ATTN: ANG YVONNE Code: ASM 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. **SLC 169P** SFM 6808H Veh. Inspected Policy No. P1803480 Coverage (\$) 0.00 Claim No. S2M042RP Excess (\$) 0.00 ANG YVONNE **Assign Date** 02/06/2022 Assign From **Vehicle Particulars & Condition** 2. **TOYOTA SIENTA 1.5X** 1496 Make & Model c.c HIDDEN 2018 Engine No. Year of Reg. NSP1707136026 SILVER Chassis No. Colour Odometer 52120 KM Steering IN ORDER **IN ORDER** STANDARD ALLOY RIM **Brakes** Modification GOOD General 3. **Conditions of Tyres** Size Make **Balance** R/H Front Tyre 185/60 R15 YOKOHAMA 6 mm YOKOHAMA L/H Front Tyre 185/60 R15 6 mm 185/60 R15 YOKOHAMA R/H Rear Tyre 6 mm YOKOHAMA L/H Rear Tyre 185/60 R15 6 mm 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. 5. **General Information** 30/05/2022 Inspect Date / Time 02/06/2022 (11:00 AM) Accident Date **GARAGE 13 PTE LTD** Survey held at 8 KAKI BUKIT AVE 4 #03-46 PREMIER 415875 SINGAPORE. 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$7,000-\$8,000 5b. **Estimate Days of Repair**

Report Ref No. CS3/ASM22005271/Vvcm4

Inspected By

B

THEVAN THOMAS KARTHIKESAVAN

ESTIMATED NORMAL PERIOD FOR REPAIR:

Asst. Automotive Assessor

L

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser

7 Working Days