

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22005276/KVY3E2

Date: 04/07/2022

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMB1SNA00008672200
Claimant Vehicle No: SMG4283H Insured Vehicle No: PC8592A
Date of Loss: 12/05/2022 Nature of Claim: TP Claim No: SNM22D203858/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMG4283H
Make & Model: RENAULT GRAND SCENIC IV, 1.5 DCI EU6 (A) Engine No: K9KF649D059016
Reg. Date: 18/12/2018 (Man. Year: 2018) Chassis No: VF1RFA00761788739
Colour: Metallic Grey Odometer: 268914 km
Engine Capacity: 1461 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/55 R20 Rear Tyre Size: 195/55 R20
Front Left Side: Tourador 5 mm Rear Left Side: Goodyear 7 mm
Front Right Side: Tourador 5 mm Rear Right Side: Goodyear 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,423.01	1,396.23	10,026.78	87.78
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,030.00	550.00	2,480.00	81.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,453.01	1,946.23	12,506.78	86.53
Approved Total (Overridden) (S\$)		1,550.00		
(S\$)	14,453.01	1,550.00	12,903.01	89.28
+ GST 7.00/7.00% (S\$)	1,011.71	108.50	903.21	89.28
Nett Amount (S\$)	15,464.72	1,658.50	13,806.22	89.28

INSPECTION

Date of Assignment: 30/06/2022
Date Inspected: 02/06/2022 Inspected At: Munich Autocare Pte Ltd (HQ)
60 Jalan Lam Huat, #07-43
Singapore 737869
Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 Jul 2022)
Parts:	M1-MPV	RENAULT GRAND SCENIC IV 1.5 DCI EU6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMG4283H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	1,748.76 F	*- FL
2	1		*FRONT BUMPER SIDE BRACKET LH	Serviceable	275.20 F	*- FL
3	1		*FRONT BUMPER SIDE BRACKET RH	Serviceable	275.20 F	*- FL
4	1		*FRONT BUMPER SIDE INNER BRACKET LH	Serviceable	226.60 F	*- FL
5	1		*FRONT BUMPER SIDE INNER BRACKET RH	Serviceable	226.60 F	*- FL
6	1		*FRONT BUMPER LOWER LIP	Cut	517.21 F	*517.21 FL
7	1		*ALLOY RIM 20 INC	Serviceable	1,405.72 F	*- FL
8	1		*FRONT HEADLAMP LH	Cut	1,034.16 F	*1,034.16 FL
9	1		*FRONT HEADLAMP BRACKET LH	Serviceable	192.84 F	*- FL
10	1		*FRONT HEADLAMP BRACKET RH	Serviceable	192.84 F	*- FL
11	1		*FRONT FENDER LH	Repair	774.72 F	*- FL
12	1		*FRONT FENDER SIDE BRACKET LH	Serviceable	271.68 F	*- FL
13	1		*FRONT CENTRE BRACE BRACKET	Serviceable	138.12 F	*- FL
14	1		*FRONT FENDER INNER PANAL OUTER	Repair	134.40 F	*- FL
15	1		*FRONT SUPPORT PANEL	Serviceable	1,293.36 F	*- FL
16	1		*FRONT FOGLAMP MOULDING (CHROME)	Serviceable	266.16 F	*- FL
17	1		*FRONT FOGLAMP COVER	Serviceable	266.16 F	*- FL
18	1		*FRONT PARKING SENSOR	Serviceable	291.60 F	*- FL
19	1		*FRONT BLIND SPOT SENSOR RH	Serviceable	457.92 F	*- FL
20	1		*FRONT BUMPER SENSOR HARNESS WIRE	Serviceable	219.72 F	*- FL
21	1		*FRONT RADIATOR TOP GARNISH	Serviceable	502.08 F	*- FL
22	1		*FRONT BUMPER LOWER REINFORCEMENT GARNISH	Serviceable	258.48 F	*- FL
23	1		*FRONT BUMPER LOWER REINFORCEMENT GARNISH	Serviceable	285.48 F	*- FL
24	7		*FRONT BUMPER CLIPS	Not Necessary	49.00 FS	*- FS
25	7		*FRONT FENDER CLIPS	Not Necessary	49.00 FS	*- FS
26	10		*RADIATOR TOP GARNISH CLIPS	Not Necessary	70.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	11,423.01	1,551.37
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	155.14
Total Parts (\$\$)	11,423.01	1,396.23

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REFIX FRONT BUMPER, FRONT FENDER LH/RH, HEADLAMP LH/RH, FOGLAMP LH/RH AND ALL AND NECESSARY ETC	New	1,500.00	150.00
2	TO REPLACE ALL SENSOR WIRE HARDNESS FOR PROPER FUNCTION INCLUDING ADJUSTMENT OF HEADLAMP LH/RH & FOG LAMP LH/RH	New	180.00	0.00
3	TUFF KOTE AND SPRAY ANTI PROOFING	New	150.00	0.00
4	TO RESPRAY FRONT ACCIDENT PORTION, BUMPER AND FENDER LH/RH	New	1,200.00	400.00
Gross Labour Cost (\$\$)			3,030.00	550.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >