#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI22005278/ETY3E2

08/06/2022 Date:

**REFERENCE** 

China Taiping Insurance (Singapore) Handling Insurer:

Pte. Ltd.

Policy No: DMPCSNW00132552100

**Claimant Vehicle** 

SBS3503Y

**Insured Vehicle** 

SMU3368E

No:

No:

Date of Loss: 11/05/2022 Nature of Claim: TP Claim No:

SNM22D203293/C02

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

**SBS3503Y** Reg No:

Make & Model: VOLVO B9TL, 9.4 D (A) Engine No: D9194632

Reg. Date: 01/12/2015 (Man. Year: 2015) Chassis No: YV3S4P929GA174620

> Odometer: 439496 km

Colour: Multi-colour **Engine Capacity:** 9364 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Footbrake (Serviceable): Yes Yes

Handbrake (Serviceable): **Engine Modification:** Pre-accident Condition: Yes Nο

**CONDITION OF TYRES** 

Front Tyre Size: 295/80 R22.5 Rear Tyre Size: 295/80 R22.5 (D) Front Left Side: Rear Left Side: Bridgestone 4/4 mm Bridgestone 4 mm Bridgestone 4 mm Front Right Side: Rear Right Side: Bridgestone 4/4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,347.72	126.38	1,221.34	90.62
Miscellaneous Items	0.00	0.00	0.00	
Labour	800.00	800.00	0.00	0.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,147.72	926.38	1,221.34	56.87
+ GST 7.00/7.00% (S\$)	150.34	64.85	85.49	56.86
Nett Amount (S\$)	2,298,06	991.23	1,306.83	56.87

**INSPECTION** 

Date of Assignment: 02/06/2022

Boxfresh Pte Ltd (HQ) 154 GUL CIRCLE Date Inspected: 03/06/2022 Inspected At:

Singapore 629611

Estimated Period of Repair: 2.0 days

DENISE TAY KWEE CHENG Adjuster: **CHEN TSUE YEE** Manager:

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Different 1 cents -Finalise confirm amount: \$926.37

### **REPAIR DETAILS**

## Reference

Part Source: (Last Synchronised: 08 Jun 2022)

Parts: N/A VOLVO B9TL 9.4 D (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SBS3503Y)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*ENGINE DOOR PANEL P/N:A12-02429	Repair	1,066.88 F	*- FL
2	1		*DOOR LATCH DEL00298 (2PCS)	Bent (1Pc Only)	280.84 F	*140.42 FL
F=Fra	nchise	part. L=ListIte	mDisc.			
				Sub Total (S\$)	1,347.72	140.42
			- List Item Discount on L Ite	ems 0.00/10.00% (S\$)	0.00	14.04
				Total Parts (S\$)	1,347.72	126.38
			Report was unsubmitted during thi	s print-out.		

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			
1	REPAIR O/S FRONT CORNER BUMPER }	New	800.00	800.00
2	SAND, PUTTY AND MAKE GOOD SURFACE OF AFFECTED PARTS }	New	0.00	0.00
3	PAINTING OF ALL NEW AND AFFECTED PARTS }	New	0.00	0.00
4	REPAIR AREA SURROUNDING ENGINE DOOR }	New	0.00	0.00
	Gross Labo	ur Cost (S\$)	800.00	800.00
	Report was unsubmitted during thi	s print-out.		

< END OF ESTIMATES >