ASS. RECORDY: Steve 1 CS/CTIQ	10052781Et43 1
ASSIGNMENT 01 Dec 2015	
From: Date:	Veh No: SBC 3503Y Yr Regn; 1
Estimated Cost:	Type: M.Car / M.Cycle / Bus) Van / Lorry / Taxl / Prime Mover /
OD ITP WE ITP RES ! OD RES ! EVA ! INV! MV	Truck / Traller or
To Inspect Vehicle No:	Make: VO VB 8976 c.c 9364
at Workshop m/s	Colour NWH-COM AC: Insured / Std / NI / NA
of	Sp.Reading 139496 T/Radio: Insured 1 Std / NI / NA
Insured:	Eng/No:
Policy No.	C/No: Y V SS 47 119 (1A) / 46 P.
Claims No.	Gen. Cond: Good / Faly / Poor / Burnt
Sum Insured: Excess:	Steering: Inorde / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorden/Jammed/Leaked/Burnt or
Make of Veh:	Modi: NII /S/Rim / STD A/Rim or
	Tyre Size: F:
(Policy Condition)	R:
Remark: The veh had commenced its N/S O/S	BS DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO / YOKO or Rear
Bal. or Market Value:	PION DIRECT / IV mm
IDAC Accident Rport: Consistent?: Yes or No	R/Bal. / mm / R/Bal. / mm
GIA / PR Seen: Consistent? : Yes or No	D.O.A. 11 577 D.O.I. 3/6/1/
Est Repairs: days Res.: Yes or No	Rafaci - July
Lum Sum: % 3 Val.: Yes or No	Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
CA / REV / REP. / 24 HRS	12/01 RM
Vernoie, my our	The U/C / Chassis frame / Body Structure affected due to collision.
Date: Person Contacted. Date / Time Action / Instruction	
Ne GIA YEPCH	
PART BY PART \$926.37	
RED: 1221.34;56%	
11221.01,007	
Dale/Time, File Pass to? : Prell. Report	Days Of Repair: 2
Final Report	Resurvey No. of Trip: Survey Fee:
- 1)	, , , , , , , , , , , , , , , , , , ,
Add F	ee: Site insp
2)	: Interview (
Reput Formal :	: Tech, Invs (\$) Others
Lump Som (LB.E. (\$	Meerand









Boxfresh Pte Ltd

7030 Ang Mo Kio Ave 5 #06-49

Northstar @AMK Singapore 569880

Tel: 64585441 Fax: 64553470

Vehicle No: SBS3503Y

Accident date: 11th May 2022

Model No: Volvo

Registered owner: Go Ahead Singapore Pte Ltd

B9tl

Date of Estimate: 02/06/22

My Ref: BF-IC-1066

Total Charge

Parts changed (Total 2 days of repair)

a) Replace engine door panel P/N:A12-02429

b) Replace door latch DEL00298 (2 pcs)

61

\$\$ 1066.88 X R \$\$ 280.84 X 140.42

Subtotal

: S\$

1347.72

Parts Repair and Labour

- c) Repair O/S front corner bumper
- d) Repair area surrounding engine door
- e) Sand, putty and make good surface of affected parts
- f) Painting of all new and affected parts.

BOXFRESH PTE LTD

WORKSHOP: 154 GUL CIRCLE SINGAPORE 629611

OFFICE: 7030 ANG MO KIO AVE 5 #06-49 NORTHSTAR SINGAPORE 569880

T: +65 64585441 • F: +65 64553470 • E: business@boxfresh.com.sg • W: www.boxfresh.com.sg









Subtotal:

S\$ 800 J

Total Charge

S\$ 2147.72

GST

S\$ 150.34

Total Bill

S\$ 2298.06

Steve CLKK) 3/6/22 , 11.300 Steve Chen @ IKKauth. com

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before after spray painting

- Third purp survey is on a 10 mout
- No illegal mouth of prints School 1
 Supplementary the issue as being mount and is subject to final approvacion on a concern or upany.

Acknowledged by Repairer

Signature:

BOXFRESH PTE LTD

WORKSHOP: 154 GUL CIRCLE SINGAPORE 629611 OFFICE: 7030 ANG MO KIO AVE 5 #06-49 NORTHSTAR SINGAPORE 569880 T: +65 64585441 • F: +65 64553470 • E: business@boxfresh.com.sg • W: www.boxfresh.com.sg