

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI22005285/RTY3E2

**Date:** 14/06/2022

### REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNA00069872106  
Claimant Vehicle No : SJY9803R Insured Vehicle No : GW4346Y  
Date of Loss: 29/04/2022 Nature of Claim: TP Claim No: SNM22D202972/C02/TANKW

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJY9803R**  
Make & Model: BMW 120I, 2.0 (A) Engine No: B717I656N46B20BD  
Reg. Date: 20/10/2010 (Man. Year: 2010) Chassis No: WBAUL52020VL55285  
Colour: Grey Odometer: 146778 km  
Engine Capacity: 1995 cc  
Market Value/New Car Price: N/A  
Sum Insured (\$\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 205/50 R17 Rear Tyre Size: 205/50 R17  
Front Left Side: Falken 6 mm Rear Left Side: Falken 6 mm  
Front Right Side: Falken 6 mm Rear Right Side: Falken 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	963.00	481.50	481.50	50.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,050.00	380.00	670.00	63.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>2,013.00</b>	<b>861.50</b>	<b>1,151.50</b>	<b>57.20</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	140.91	60.31	80.60	57.20
<b>Nett Amount (\$\$)</b>	<b>2,153.91</b>	<b>921.81</b>	<b>1,232.10</b>	<b>57.20</b>

### INSPECTION

Date of Assignment: 02/06/2022  
Date Inspected: 03/06/2022 Inspected At: Tan Chong Motor Sales Pte Ltd (Bukit Timah)  
911, Bukit Timah Road  
Singapore 589622  
Estimated Period of Repair: 2.0 days

**Adjuster:** MOHD RASUL

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 14 Jun 2022)
Parts:	143	BMW 120I 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJY9803R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*MIRROR (HEATED) GLASS	Cracked	211.00 FS	*105.50 FS
2	1		*SUNDRIES	Necessary	10.00 FS	*5.00 FS
3	1		*R/F MIRROR COVER	Missing	116.00 FS	*58.00 FS
4	1		*R/F MIRROR ASSY	Cracked	626.00 FS	*313.00 FS
F=Franchise part. S=SpcNett.						
Total Parts (S\$)					963.00	481.50

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	CHECK ELECTRONIC	New	240.00	0.00
2	RENEW RH WING MIRROR ASSY	New	390.00	195.00
3	S/PAINT WING MIRROR COVER	New	300.00	125.00
4	REMOVE TRIMBOARD FINISHER TO ASSIST REPAIR	New	120.00	60.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,050.00</b>	<b>380.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >