

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22005285/RTY3E2**Date:** 05/09/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNA00069872106
Claimant Vehicle No :	SJY9803R	Insured Vehicle No :	GW4346Y
Date of Loss:	29/04/2022	Nature of Claim:	TP
		Claim No:	SNM22D202972/C02/TANKW

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJY9803R	Engine No:	B7171656N46B20BD
Make & Model:	BMW 120I, 2.0 (A)	Chassis No:	WBAUL52020VL55285
Reg. Date:	20/10/2010 (Man. Year: 2010)	Odometer:	146778 km
Colour:	Grey		
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/50 R17	Rear Tyre Size:	205/50 R17
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	963.00	963.00	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,050.00	760.00	290.00	27.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	2,013.00	1,723.00	290.00	14.41
+ GST 7.00/7.00% (\$\$)	140.91	120.61	20.30	14.41
Nett Amount (\$\$)	2,153.91	1,843.61	310.30	14.41

INSPECTION

Date of Assignment:	02/06/2022	
Date Inspected:	03/06/2022	Inspected At: Tan Chong Motor Sales Pte Ltd (Bukit Timah) 911, Bukit Timah Road Singapore 589622
Estimated Period of Repair:	2.0 days	

Adjuster: MOHD RASUL**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

SPECIAL REMARKS

NOTE: 50-50 AS AGREED BETWEEN INSURANCE AND REPAIRER.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Sep 2022)
Parts:	143	BMW 120I 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	LKK Auto Consultants Pte Ltd/SJY9803R/05/09/2022 11:31	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*MIRROR (HEATED) GLASS	Cracked	211.00 F	*211.00 F
2	1		*SUNDRIES	Necessary	10.00 F	*10.00 F
3	1		*R/F MIRROR COVER	Missing	116.00 F	*116.00 F
4	1		*R/F MIRROR ASSY	Cracked	626.00 F	*626.00 F
					Total Parts (S\$)	963.00
						963.00

F=Franchise part.

LKK Auto Consultants Pte Ltd/SJY9803R/05/09/2022 11:31. Not valid without Reference section.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK ELECTRONIC	New	240.00	0.00
2	RENEW RH WING MIRROR ASSY	New	390.00	390.00
3	S/PAINT WING MIRROR COVER	New	300.00	250.00
4	REMOVE TRIMBOARD FINISHER TO ASSIST REPAIR	New	120.00	120.00
Gross Labour Cost (\$\$)			1,050.00	760.00

LKK Auto Consultants Pte Ltd/SJY9803R/05/09/2022 11:31. Not valid without Reference section.

< END OF ESTIMATES >