

## COMFORT TRANSPORTATION PTE LTD

## REPAIR ESTIMATE

Vehicle No. : SHC3413L

Make : HYUNDAI

Model : IONIQ(G2)

Date: 02.06.2022

Insurance: NTUC

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	REAR BUMPER COVER / <i>ll</i>			\$459.40 ✓
10	REAR BUMPER CLIPS / <i>ll</i>			\$22.00 ✓
1	REAR BUMPER CENTRE MOULDING ASSY / <i>ll</i>			\$451.25 ✓
1	REAR BUMPER REINFORCEMENT <i>X NN</i>			\$394.80
1	REAR BUMPER REINFORCEMENT BRACKET LH RH <i>? ✓</i>	BT	138.1 ✓	\$276.20
1	ANTENNA SMARTKEY <i>X NN</i>			\$40.50
1	REAR BUMPER FOG LAMP <i>✓ BR</i>			\$201.50 ✓
1	LICENCE LAMP <i>X NN</i>			\$85.30
1	REAR BUMPER LOWER CENTER MOULDING <i>✓ BR</i>			\$155.00 ✓
SUB TOTAL				\$2,085.95 1427.5
LESS 20%				\$417.19
DISCOUNTED TOTAL				\$1,668.76 1142
	REAR BUMPER RUBBER MAT / <i>ll</i>			\$50.00 ✓
	REAR NUMBER PLATE WITH TRIM COVER / <i>BT</i>		-10%	\$55.00 ✓
	REAR BUMPER REVERSE SENSOR <i>X NN</i>		-10%	\$180.00
				\$285.00
Labour Charge				
PANEL BEATING				\$750.00 350
SPRAY PAINTING CHARGE				\$300.00 250
CHECK ALL LIGHTING				\$60.00 X M
REMOVE/REFIX REVERSE SENSOR				\$80.00 40
TOTAL LABOUR				\$1,190.00
ESTIMATE TOTAL				\$3,143.76
				1887
				-20%: 1500

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

2 Days.  
4/5  
After repair photos.  
Gina Qian  
2/6/22 4:30pm

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal importation is allowed
- Supplier of parts must be resurveyed and is subject to approval by the insurance company

Acknowledged by:

Signature:

Date: