

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22005294/UQY3N2**Date:** 13/06/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNA00115702103
Claimant Vehicle No :	SME6936E	Insured Vehicle No :	GBH9376R
Date of Loss:	31/05/2022	Nature of Claim:	TP
		Claim No:	SNM22D203869/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SME6936E	Engine No:	2NRX402563
Make & Model:	TOYOTA VIOS, 1.5 (A)	Chassis No:	MR2B23F3301160043
Reg. Date:	28/12/2018 (Man. Year: 2018)	Odometer:	180793 km
Colour:	Brown		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60R15	Rear Tyre Size:	185/60R15
Front Left Side:	Evotechno 6 mm	Rear Left Side:	Evotechno 6 mm
Front Right Side:	Evotechno 6 mm	Rear Right Side:	Evotechno 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,049.30	2,083.35	965.95	31.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,330.00	1,120.00	210.00	15.79
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,379.30	3,203.35	1,175.95	26.85
Approved Total (Overridden) (S\$)		2,500.00		
Nett Amount (S\$)	4,379.30	2,500.00	1,879.30	42.91

INSPECTION

Date of Assignment:	07/06/2022	
Date Inspected:	03/06/2022	Inspected At: Bethlehem Auto (HQ) Blk 5035 Ang Mo Kio Industrial Park 2, #01-371 Singapore 569538
Estimated Period of Repair:	4.0 days	

Adjuster: MARCUS CHUA**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 13 Jun 2022)
Parts:	143	TOYOTA VIOS 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SME6936E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented/Deformed	420.00 F	*420.00 FL
2	1		*REAR BOOTLID	Dented/Bent	580.00 F	*580.00 FL
3	1		*REAR SIDE RETAINER	Necessary	220.00 F	*220.00 FL
4	1		*REAR SENSOR	O/s Shorted	430.00 F	*198.50 FL
5	1		*BOOTLID INNER LOCK	Twisted	95.00 F	*95.00 FL
6	1		*SET REAR BUMPER CLIPS	Necessary	35.00 F	*35.00 FL
7	1		*REAR NUMBER PLATE COVER	Serviceable	40.00 F	*- FL
8	1		*REAR BUMPER BEAM	Dented	353.10 F	*353.10 FL
9	2		*BOOTLID REFLECTORS	Cracked	876.20 F	*876.20 FL
					Sub Total (\$\$)	3,049.30 2,777.80
					- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00 694.45
					Total Parts (\$\$)	3,049.30 2,083.35

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	MUDGUARD PANEL BEATING	New	680.00	520.00
2	PAINTING LABOUR	New	650.00	600.00
Gross Labour Cost (S\$)			1,330.00	1,120.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >