

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG22005298/RNY3E2**Date:** 04/05/2023REFERENCE

Insured/Claimant:	WONG YEOW KIM	Policy No:	A29128153QMX	
Date of Loss:	31/05/2022	Nature of Claim:	OD	Claim No: 641613

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJR7311T	Engine No:	1NZX917167
Make & Model:	TOYOTA VIOS, 1.5 E (A)	Chassis No:	MR053HY9305115777
Reg. Date:	10/07/2009 (Man. Year: 2009)	Odometer:	149714 km
Colour:	Grey		
Engine Capacity:	1497 cc		
Market Value/New Car Price:	S\$20,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/55 R15	Rear Tyre Size:	195/55 R15
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,292.30	8,310.50	1,981.80	19.26
Miscellaneous Items	70.00	70.00	0.00	0.00
Labour	2,430.00	2,180.00	250.00	10.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,792.30	10,560.50	2,231.80	17.45
- Excess (S\$)	500.00	500.00	0.00	0.00
(S\$)	12,292.30	10,060.50	2,231.80	18.16
+ GST 7.00/8.00% (S\$)	860.46	804.84	55.62	6.46
Nett Amount (S\$)	13,152.76	10,865.34	2,287.42	17.39

INSPECTION

Date of Assignment:	03/06/2022	Present Location:	Automotive Repair Centre Pte Ltd (HQ)
Date Inspected:	03/06/2022	Inspected At:	Automotive Repair Centre Pte Ltd (HQ)
Estimated Period of Repair:	12.0 days		38 Woodlands Industrial Park E1, #05-18
			Singapore 757700

Adjuster: MOHD RASUL**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 May 2023)
Parts:	143	TOYOTA VIOS 1.5 E (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJR7311T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*Parts		8,690.70 F	*5,801.00 F
<u>Supplementary #1</u>						
2	1		*Sub- Parts		1,601.60 F	*1,754.00 F
F=Franchise part.						
Sub Total (\$\$)					10,292.30	7,555.00
+ Margin on L,N Items 0.00/10.00% (\$\$)					0.00	755.50
Total Parts (\$\$)					10,292.30	8,310.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	Coolant 4L (NECESSARY)	35.00	35.00
2	1	Front Number Plate (CRACKED)	35.00	35.00
Sub Total (\$)			70.00	70.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	General Labor Subtotal	New	1,710.00	1,580.00
2	Paint Labor Subtotal	New	720.00	600.00
Gross Labour Cost (\$)			2,430.00	2,180.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >