

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22005301/ENY3Q2**Date:** 15/09/2022REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00011972201
Claimant Vehicle No : PC3852H **Insured Vehicle No :** GBE5658U
 Date of Loss: 31/05/2022 Nature of Claim: TP Claim No: SNM22D203833/C02/IRENE

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **PC3852H**
 Make & Model: MERCEDES-BENZ VIANO, 3.7 (A) Engine No: 65194032206908
 Reg. Date: 07/09/2015 (Man. Year: 2014) Chassis No: WDF63981523889072
 Colour: Black Odometer: 392991 km
 Engine Capacity: 2143 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195/60 R15 Rear Tyre Size: 195/60 R15
 Front Left Side: Bridgestone 5 mm Rear Left Side: Bridgestone 5 mm
 Front Right Side: Bridgestone 5 mm Rear Right Side: Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,428.60	9,090.20	10,338.40	53.21
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,070.00	3,020.00	1,050.00	25.80
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	23,498.60	12,110.20	11,388.40	48.46
Approved Total (Overridden) (S\$)		9,700.00		
Nett Amount (S\$)	23,498.60	9,700.00	13,798.60	58.72

INSPECTION

Date of Assignment: 03/06/2022
 Date Inspected: 10/06/2022 Inspected At: Win Automotive Services
 60 Jalan Lam Huat #04-53
 Singapore 737869
 Estimated Period of Repair: 8.0 days

Adjuster: CHEN TSUE YEE**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS**Reference**

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 15 Sep 2022)
Parts: 143	MERCEDES-BENZ VIANO 3.7 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for PC3852H)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	850.00 FL	*850.00 FL
2	2		*REAR LH & RH SIDE BUMPER GARNISH	Dented	500.00 FL	*500.00 FL
3	2		*REAR LH & RH BUMPER REFLECTOR LAMP	Not Necessary	100.00 FL	*- FL
4	2		*REAR BUMPER SIDE RETAINER	Broken	180.00 FL	*180.00 FL
5	1		*SET REAR BUMPER FASTENERS	Necessary	55.00 FL	*30.00 FL
6	1		*REAR BUMPER REINFORCEMENT (LH & RH END PANEL BRACKET)	Bent	500.00 FL	*200.00 FL
7	1		*REAR BUMPER TOWING COVER	Not Necessary	98.00 FL	*- FL
8	1		*REAR BUMPER INNER CENTER FRAME	Broken	180.00 FL	*180.00 FL
9	1		*REAR BUMPER INNER SWITCH SENSOR MODULE BRACKET	Not Necessary	200.00 FL	*- FL
10	1		*BOOTLID	Dented	3,120.00 FL	*2,550.00 FL
11	1		*BOOTLID INNER LOCK	Jammed	290.00 FL	*290.00 FL
12	1		*BOOTLID INNER TRIM	Broken	360.00 FL	*360.00 FL
13	1		*BOOTLID INNER TRIM FASTENERS	Necessary	28.00 FL	*28.00 FL
14	1		*BOOTLID CHROME MOULDING	Cut	180.00 FL	*180.00 FL
15	1		*BOOTLID LOGO EMBLEM	Necessary	95.00 FL	*95.00 FL
16	2		*BOOTLID LH & RH SHOCK ABSORBER	Not Necessary	420.00 FL	*- FL
17	1		*BOOTLID OUTER LOCK HANDLE ACCURATOR	Jammed	180.00 FL	*180.00 FL
18	1		*VIANO EMBLEM	Necessary	95.00 FL	*95.00 FL
19	2		*TAILLAMP LH & RH ASSY	Cut	880.00 FL	*880.00 FL
20	2		*TAILLAMP LH & RH LOWER BRACKET HOLDER	Not Necessary	195.00 FL	*- FL
21	1		*REAR FLOOR PANEL	Repair	1,680.00 FL	*- FL
22	1		*REAR WINDSCREEN	Broken	920.00 FL	*920.00 FL
23	1		*REAR WINDSCREEN WIPER ASSY	Broken / Jammed	550.00 FL	*550.00 FL
24	1		*REAR END PANEL (INNER & OUTER)	Dented	750.00 FL	*750.00 FL
25	1		*REAR END PANEL TOP GARNISH	Broken	260.00 FL	*260.00 FL
26	1		*REAR END PANEL TOP GARNISH FASTENERS	Necessary	30.00 FL	*30.00 FL
27	2		*REAR FENDER LH & RH INNER TRIM BOARD	Not Necessary	6,000.00 FL	*- FL
28	1		*SET REAR FENDER LH & RH INNER TRIM BOARD FASTENERS	Necessary	58.00 FL	*20.00 FL
29	1		*REAR EXHAUST MUFFLER	Not Necessary	1,300.00 FL	*- FL
30	2		*REAR FENDER LH & RH TOP INNER TRIM BOARD	Crushed	600.00 FL	*600.00 FL
31	1		*REAR END PANEL SEALANT	Necessary	80.00 FS	*30.00 FS
32	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
33	1		*REVERSE SENSOR	Shorted	200.00 FS	*200.00 FS
34	1		*REVERSE CAMERA	Not Necessary	300.00 FS	*- FS
35	1		*REAR CAR PLATE AND HOUSING	Cut	50.00 FS	*40.00 FS
36	1		*REAR FLOOR PANEL SEALANT	Not Necessary	80.00 FS	*- FS
37	1		*REAR 70KM/H STICKER LABEL	Necessary	50.00 FS	*25.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	21,494.00	10,063.00
- List Item Discount on L Items 10.00/10.00% (S\$)	2,065.40	972.80
Total Parts (S\$)	19,428.60	9,090.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT AND RENEWAL OF ALL NECESSARY DAMAGED BODY PARTS	New	1,400.00	1,300.00
2	TO CHECK WIRING AND REWIRE	New	60.00	50.00
3	TO REMOVE AND REINSTALL /REALIGN REAR EXHAUST	New	120.00	0.00
4	TO REMOVE AND REINSTALL REVERSE SENSOR AND REVERSE CAMERA	New	120.00	30.00
5	TO ANTI-RUST	New	120.00	30.00
6	TO REMOVE AND REINSTALL BOOTLID COMPONENTS	New	100.00	80.00
7	TO PUTTY AND SPRAY PAINT OF AFFECTED AREAS	New	1,400.00	1,300.00
8	TO CLEAR /RESET FAULT CODE	New	250.00	120.00
9	TO REMOVE AND REINSTALL REAR BOOT UPHOLSTERY	New	100.00	80.00
10	TO REALIGN REAR CHASSIS MEMBER	New	250.00	0.00
11	TO REMOVE AND REINSTALL REAR WINDSCREEN CONDUCT WATER TEST LEAK	New	150.00	30.00
Gross Labour Cost (S\$)			4,070.00	3,020.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >