

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG22005310/DNY3E2**Date:** 13/10/2022REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1001062030		
Claimant Vehicle No :	SLQ4304R	Insured Vehicle No :	SLE9579U		
Date of Loss:	31/05/2022	Nature of Claim:	TP	Claim No:	275650

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLQ4304R	Engine No:	R16A14003497
Make & Model:	HONDA CIVIC, 1.6 L (A)	Chassis No:	JHMFD46209S200939
Reg. Date:	16/11/2009 (Man. Year: 2008)	Odometer:	189820 km
Colour:	Black		
Engine Capacity:	1595 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	21,401.10	3,598.72	17,802.38	83.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,870.00	1,410.00	5,460.00	79.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	28,271.10	5,008.72	23,262.38	82.28
Approved Total (Overridden) (\$\$)		4,000.00		
(\$\$)	28,271.10	4,000.00	24,271.10	85.85
+ GST 7.00/7.00% (\$\$)	1,978.98	280.00	1,698.98	85.85
Nett Amount (\$\$)	30,250.08	4,280.00	25,970.08	85.85

INSPECTION

Date of Assignment:	03/06/2022	JWG International Pte Ltd (HQ)
Date Inspected:	03/06/2022 Inspected At:	Blk 10, Ang Mo Kio Ind Park 2A,, #03-08 AMK
		AutoPoint
		Singapore 568047
Estimated Period of Repair:	5.0 days	

Adjuster: BRYAN TANI**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 11 Oct 2022)
Parts:	143	HONDA CIVIC 1.6 L (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLQ4304R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Dented	1,516.05 FL	*810.70 FL
2	1		*BOOTLID LAMP LH / RH	N/S Cracked / O/S Not Necessary	806.60 FL	*374.20 FL
3	1		*BOOTLID HONDA LOGO	Necessary	88.55 FL	*30.20 FL
4	1		*BOOTLID CIVIC EMBLEM	Necessary	93.65 FL	*45.00 FL
5	1		*BOOTLID LOCK	Damaged	391.75 FL	*287.60 FL
6	1		*BOOTLID LOCK CATCH	Repair	123.00 FL	*- FL
7	1		*BOOTLID SWITCH	Not Necessary	312.50 FL	*- FL
8	1		*BOOTLID INNER TRIM	Not Necessary	400.55 FL	*- FL
9	2		*BOOTLID HINGE LH / RH	Not Necessary	345.80 FL	*- FL
10	1		*TAIL LAMP LH / RH O/S NOT NECESSARY	N/S Mtg Cracked / Cut	1,326.10 FL	*452.00 FL
11	2		*TAIL LAMP PANEL LH / RH	Not Necessary	997.10 FL	*- FL
12	2		*TAIL LAMP LOWER BRACKET LH / RH	Serviceable	312.00 FL	*- FL
13	2		*REAR BUMPER SIDE RETAINER LH / RH	Serviceable	83.80 FL	*- FL
14	1		*REAR END PANEL	Dented	1,050.75 FL	*536.00 FL
15	1		*REAR END PANEL TOP GARNISH	Deformed / Bent	354.12 FL	*186.00 FL
16	1		*REAR FENDER LH	Not Necessary	1,812.75 FL	*- FL
17	1		*REAR FENDER AIR DUCT LH	Not Necessary	72.00 FL	*- FL
18	1		*REAR FENDER INNER TRIM LH	Deformed	518.85 FL	*343.80 FL
19	1		*REAR FENDER INNER SHIELD LH	Not Necessary	143.00 FL	*- FL
20	1		*REAR WHEEL HOUSING LH	Not Necessary	2,199.00 FL	*- FL
21	1		*SPARE WHEEL PANEL	Not Necessary	1,488.30 FL	*- FL
22	2		*SPARE WHEEL QUARTER PANEL LH	Not Necessary	720.00 FL	*- FL
23	1		*SPARE WHEEL TOP BOARD	Bent	474.00 FL	*298.80 FL
24	1		*SPARE WHEEL STYROFOAM	Not Necessary	372.90 FL	*- FL
25	1		*REAR EXHAUST PIPE	Not Necessary	1,471.30 FL	*- FL
26	1		*REAR EXHAUST MOUNTING	Not Necessary	124.75 FL	*- FL
27	1		*REAR EXHAUST HEAT SHIELD	Not Necessary	165.70 FL	*- FL
28	1		*REAR WINDSCREEN MOULDING	Not Necessary	249.00 FL	*- FL
29	1		*SET REAR REVERSE SENSOR	Not fitted	300.00 FS	*- FS
30	1		*REAR BUMPER (TYPE R) MODEL	Dented / Cracked	2,300.00 F	*1,021.60 FN
31	1		*REAR BUMPER LOWER DIFFUSER (TYPE R) MODEL	Not Necessary	1,200.00 FS	*- FS
32	1		*BOOTLID TOP SPOILER	Not Necessary	1,500.00 FS	*- FS
33	1		*BOOTLID TOP SPOILER BRACKET	Not Necessary	300.00 FS	*- FS
34	1		*REVERSE CAMERA	Not Necessary	600.00 FS	*- FS
35	1		*REAR END PANEL SEALANT	Necessary	80.00 FS	*40.00 FS
36	1		*REAR FENDER SEALANT	Not Necessary	80.00 FS	*- FS
37	1		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
38	1		*REAR WINDSCREEN DAMPING SEAL	Not Necessary	30.00 FS	*- FS
39	1		*REAR WINDSCREEN INNER SHIELD	Not Necessary	80.00 FS	*- FS
40	1		*REAR FENDER QUARTER GLASS SEALANT	Not Necessary	80.00 FS	*- FS
41	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*20.00 FS
42	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	50.00 FS	*15.00 FS
43	1		*RAER FENDER INNER TRIM CLIPS	Necessary	50.00 FS	*15.00 FS

Report was unsubmitted during this print-out.

10/13/22, 9:44 AM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
44	1		*REAR FENDER INNER SHIELD CLIPS	Not Necessary	50.00 FS	*- FS
45	1		*REAR WHEEL HOUSING SEALANT	Not Necessary	80.00 FS	*- FS
46	1		*SPARE WHEEL PANEL SEALANT	Not Necessary	80.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.						
Sub Total (\$)					25,003.87	4,475.90
- List Item Discount on L Items 20.00/20.00% (\$)					3,602.77	672.86
- Nett Item Discount on N Items 0.00/20.00% (\$)					0.00	204.32
Total Parts (\$)					21,401.10	3,598.72
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ALL INTERIOR UPHOLSTERLY ITEMS TO FACILIATE REPAIRS	New	300.00	80.00
2	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	New	2,400.00	600.00
3	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	New	2,400.00	600.00
4	TO TUFF COAT DAMAGED AREAS	New	300.00	40.00
5	TO RNR REVERSE CAMERA	New	100.00	0.00
6	TO RNR REAR WINDSCREEN TO ASSIST WORK LOAD	New	300.00	0.00
7	TO RNR REAR BOOT MECHANISM TO ASSIST WORK LOAD	New	200.00	60.00
8	TO RNR EXHAUST SYSTEM AND ATTACHMENT PARTS	New	250.00	0.00
9	TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS	New	200.00	30.00
10	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS. RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	New	300.00	0.00
11	TO RNR REVERSE SENSOR TO ASSIST WORK LOAD	New	120.00	0.00
Gross Labour Cost (S\$)			6,870.00	1,410.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >