

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT LONPAC INSURANCE BHD Ref: CS3/LPC22005311/Rqy3m4 300 BEACH ROAD Date: 22/07/2022 #17-04/07 THE CONCOURSESINGAPORE 199555 Code: LPC2 1. Policy Particulars :- (THIRD PARTY CLAIM) Insured Veh. XD 2890D SLF 8815P Veh. Inspected Policy No. Coverage (\$) 0.00 Claim No. 22/22/22/VC05/025884 Excess (\$) 0.00 03/06/2022 **GERALD POH Assign From Assign Date** 2. **Vehicle Particulars & Condition** HONDA SHUTTLE 0 Make & Model C.C HIDDEN Engine No. Year of Reg. GK81005695 **GREY** Chassis No. Colour 093347 KM Odometer Steering IN ORDER **IN ORDER** SPORTS RIM **Brakes** Modification **FAIR** General 3. **Conditions of Tyres** Size Make **Balance** R/H Front Tyre 185/60 R15 MICHELIN 6 mm 185/60 R15 **MICHELIN** L/H Front Tyre 6 mm 185/60 R15 **MICHELIN** R/H Rear Tyre 6 mm **MICHELIN** L/H Rear Tyre 185/60 R15 6 mm 4. **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION. 5. **General Information** 02/06/2022 20/06/2022 (11:56 AM) **Accident Date** Inspect Date / Time 38 WOODLANDS RD #06-03, WOODLANDS IND PARK E1 Survey held at Repairer HWA PENG AUTO SERVICE (1996) 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.

Report Ref No. CS3/LPC22005311/Rgy3m4

THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.

C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

Inspected By

Automotive Assessor

MOHAMMED RASUL BIN MOHD YUNUS

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser