



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMN 6082X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER	TO REPAIR SEE LABOUR	529.60	-
1	FRONT BUMPER SIDE RETAINER LH	SERVICEABLE	14.20	-
1	FRONT FENDER LH	BENT	368.20	368.20
1	FRONT FENDER SHIELD LH	DISTORTED	88.40	88.40
1	LH SIDE MIRROR ASSY	TO REPAIR SEE LABOUR	507.90	-
1	FRONT LH DOOR	BENT	848.30	848.30
1	FRONT LH DOOR HINGE	TO REPAIR SEE LABOUR	89.40	-
1	FRONT LH DOOR CHECKER	SERVICEABLE	89.40	-
1	SET FRONT LH DOOR STICKER	NECESSARY	88.70	88.70
1	FRONT LH DOOR PILLAR STICKER	NECESSARY	250.00	51.80
1	FRONT LH DOOR INNER TRIM BOARD	SERVICEABLE	890.40	-
1	FRONT LH RIM COVER	CRACKED	170.20	170.20
1	FRONT LH DOOR RUBBER	SERVICEABLE	180.00	-
1	LH ROCKER PANEL	TO REPAIR SEE LABOUR	348.00	-
	LESS 20% DISCOUNT		-	-323.12
	COST PLUS 20%		892.54	-
			5,355.24	1,292.48
<u>SPECIAL NETT ITEMS</u>				
1	SET FRONT BUMPER CLIPS (SN)	NOT NECESSARY	45.00	-
1	SET FRONT LH INNER DOOR COMPARTMENT CLIPS (SN)	NOT NECESSARY	50.00	-
1	SET FRONT LH FENDER SHIELD CLIPS (SN)	NECESSARY	50.00	50.00
1	RIM (LOCAL PURCHASE) (SN)	DENTED	1,000.00	80.00
1	RIM COVER (SN)	REPEATED	300.00	-
			1,445.00	130.00
<u>LABOUR</u>				
	SPRAY PAINT ON ALL AFFECTED AREA.		1,000.00	880.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR REMOVE/REFIX ACCIDENT DAMAGE PARTS TO KNOCK, JACK, CUT WELD AND REALIGN ACCIDENT AFFECTED AREA. INCLUSIVE OF THE REPAIR OF FRONT BUMPER, LH SIDE MIRROR ASSY, FRONT LH DOOR HINGE AND LH ROCKER PANEL.		1,000.00	600.00
	TO CHECK WIRING SYSTEM & LIGHT.		100.00	20.00
	TO APPLY ANTI RUST TREATMENT.		120.00	60.00
	TO REMOVE/REFIX REVERSE SENSOR.	NOT NECESSARY	150.00	-
	TO REMOVE/REFIX FRONT LH WINDOW GLASS, MECHANISM & ETC TO NEW DOOR.		180.00	60.00
			2,550.00	1,620.00
GRAND TOTAL			9,350.24	3,042.48
RECOMMENDED COST OF REPAIRS				3,042.48

Report Ref No. CS/AGI22005312/Kty3m4

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.