

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLX 6283S

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT DOOR GLASS LH (CONSISTENT)	SCRATCHED	871.50	680.00
1	FRONT DOOR LH (CONSISTENT)	DENTED	1,890.60	1,300.00
1	FRONT DOOR RUBBER (CONSISTENT)	CUT	255.80	255.80
1	FRONT DOOR OUTER HANDLE (CONSISTENT)	SERVICEABLE	78.20	-
1	SIDE MIRROR LH (CONSISTENT)	CRACKED	1,477.60	1,159.00
1	SIDE MIRROR COVER LH (CONSISTENT)	SCRATCHED	84.80	84.80
1	FRONT DOOR LOWER MOULDING LH (CONSISTENT)	NECESSARY	39.70	39.70
1	FRONT DOOR LOWER PROTECTOR LH (CONSISTENT)	NECESSARY	182.40	182.40
1	FRONT DOOR INNER LOCK (CONSISTENT)	SERVICEABLE	528.60	-
1	FRONT DOOR OUTER TOP MOULDING (CONSISTENT)	NECESSARY	154.80	154.80
1	FRONT DOOR POWER WINDOW REGULATOR GEAR (CONSISTENT)	SERVICEABLE	234.40	-
1	FRONT DOOR POWER WINDOW MOTOR (CONSISTENT)	SERVICEABLE	608.80	-
1	REAR DOOR LH (CONSISTENT)	DENTED	1,640.20	1,250.00
1	REAR DOOR LOWER MOULDING (CONSISTENT)	NECESSARY	39.70	39.70
1	REAR DOOR LOWER PROTECTOR LH (CONSISTENT)	NECESSARY	188.60	188.60
1	REAR DOOR TOP MOULDING (CONSISTENT)	NECESSARY	155.80	155.80
1	REAR DOOR RUBBER (CONSISTENT)	SERVICEABLE	245.80	-
	LESS 25% DISCOUNT		-2,169.33	-1,372.65
			6,507.97	4,117.95
	<u>LABOUR</u>			
	TO REMOVE REPLACE /TRANSFER DOORS MECHANISM ETC.		300.00	160.00
	TO SPRAY PAINTING.		800.00	500.00
	TO REPAIR DAMAGES.		800.00	500.00
	TO CHECK WIRING WORKS.		200.00	30.00
			2,100.00	1,190.00
	GRAND TOTAL		8,607.97	5,307.95

Report Ref No. CS/ASM22005313/Vcy3m4



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		4,200.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS/ASM22005313/Vcy3m4



THEVAN THOMAS KARTHIKESAVAN

Asst. Automotive Assessor



ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser