

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22005314/KQY3M4**Date:** 23/06/2022REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSN00119112101

Claimant Vehicle No : SMR4496C **Insured Vehicle No :** YP8351D

Date of Loss: 25/05/2022 Nature of Claim: TP Claim No: SNM22D203740/C02/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMR4496C**

Make & Model: HYUNDAI AD AVANTE, 1.6 GLS (A) Engine No: G4FGKU476523

Reg. Date: 07/01/2020 (Man. Year: 2019) Chassis No: KMHD841CMLU012748

Colour: White Odometer: 88728 km

Engine Capacity: 1591 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 215/45 R17 Rear Tyre Size: 215/45 R17

Front Left Side: Continental 7 mm Rear Left Side: Continental 6 mm

Front Right Side: Continental 7 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	724.00	559.00	165.00	22.79
Miscellaneous Items	235.00	235.00	0.00	0.00
Labour	1,120.00	800.00	320.00	28.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,079.00	1,594.00	485.00	23.33
+ GST 7.00/7.00% (S\$)	145.53	111.58	33.95	23.33
Nett Amount (S\$)	2,224.53	1,705.58	518.95	23.33

INSPECTION

Date of Assignment: 07/06/2022 Present Location: Cheng Hoe Motor Pte Ltd (Yishun)

Date Inspected: 06/06/2022 Inspected At: Cheng Hoe Motor Pte Ltd (Yishun)
Blk 1019 #01-374/382, Yishun Industrial Park A
Singapore 768761

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 23 Jun 2022)

Parts: 143 HYUNDAI AD AVANTE 1.6 GLS (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMR4496C)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*1 PC REAR BUMPER	Buckled / Cracked	320.00 F	*320.00 F
2	1		*1 PC REAR BUMPER REINFORCEMENT	Repair	165.00 F	*- F
3	1		*1 PC REAR BUMPER LOWER	Mtg Cracked	175.00 F	*175.00 F
4	1		*6 PCS REAR BUMPER CLIPS @2/PC	Necessary	12.00 F	*12.00 F
5	1		*1 PC TAILGATE LOGO	Necessary	22.00 F	*22.00 F
6	1		*1 PC TAILGATE EMEBLEM (AVANTE)	Necessary	30.00 F	*30.00 F

F=Franchise part.

Total Parts (\$) **724.00** **559.00**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	1 SET REVERSE SENSOR	200.00	200.00
Supplementary #1				
2	1	REAR NO.PLATE	35.00	35.00
Sub Total (\$\$)			235.00	235.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	480.00	320.00
2	PUTTY & RESPRAY ON REAR BOOT,REAR BUMPER,REAR PANEL	New	600.00	440.00
3	REMOVE & REFIX REAR SENSOR,REAR CAMERA AND RESET SYSTEM	New	40.00	40.00
Gross Labour Cost (\$\$)			1,120.00	800.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >