



簡福星摩多工廠

KAN FOOK SING MOTOR WORKSHOP

Headquater: 61, Defu Lane 12 Singapore 539147

Tel: (65) 6747 9560, 6743 5344 Fax: (65) 6748 1006, 6281 8428

Branch: 1 Kaki Bukit Avenue 6 #01-13 Singapore 417883

Tel: (65) 6481 5150 Fax: (65) 6481 8683

E-mail: ryan@kanfs.net/ patricia@kanfs.net

UNITED OVERSEAS INSURANCE LTD
146 ROBINSON ROAD
#02-01 UOI BUILDING
SINGAPORE 068909

VEHICLE NO. : YQ1816X
ACCIDENT DATE : 31-05-2022 09:40
THIRD PARTY REF. : SHA4164J

ATTN: MOTOR CLAIMS DEPT.

SUPPLEMENTARY COST OF REPAIR TO VEHICLE YQ1816X HINO XZU710R 14FT WIDE

#	QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
1	1	FRONT BUMPER REINFORCEMENT BRACKET <i>Bent.</i>	80.00 ✓
2	1	FRONT AIR DUCT <i>Replaced.</i>	150.00 ✓
3	1	FRONT BUMPER FOGLAMP RH <i>cracked.</i>	220.00 ✓
			450.00
ADD 10%			45.00
			495.00
SUPPLEMENTARY TOTAL			495.00