



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKT 4266M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR TAIL-GATE	TO REPAIR SEE LABOUR	1,475.10	-
1	REAR TAIL-GATE GLASS MOULDING	NOT NECESSARY	85.20	-
1	REAR TAIL-GATE EMBLEM "MOBILIO"	NECESSARY	48.10	48.10
1	REAR TAIL-GATE EMBLEM "I-VTEC"	NECESSARY	35.70	35.70
1	REAR TAIL-GATE EMBLEM "RS"	NECESSARY	26.90	26.90
1	REAR O/S FENDER INNER TRIM BOARD	SERVICEABLE	387.10	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	455.60	-
1	REAR END PANEL INNER GARNISH	SERVICEABLE	135.70	-
1	REAR SPARE TYRE BOARD	SERVICEABLE	205.10	-
1	REAR BUMPER	BUCKLED	497.30	497.30
1	REAR BUMPER CHROME MOULDING	CRACKED	187.20	187.20
1	REAR BUMPER FOAM RH	CRACKED	187.10	51.10
2	REAR BUMPER REFLECTOR @\$55.10	O/S CRACKED	110.20	55.10
1	REAR EXHAUST SILENCER	DISTORTED / BENT	483.40	483.40
	LESS 20% DISCOUNT		-863.94	-276.96
			3,455.76	1,107.84
<b><u>SPECIAL NETT ITEMS</u></b>				
1	REAR REVERSE SENSOR (SN)	SERVICEABLE	200.00	-
1	REAR TAIL-GATE GLASS SEALANT (SN)	NOT NECESSARY	40.00	-
15	BUMPER CLIP @\$2.00 (SN)	NECESSARY	30.00	30.00
			270.00	30.00
<b><u>LABOUR</u></b>				
	TO PUTTY & SPRAY PAINT ON ACCIDENT AFFECTED PORTION.		1,000.00	400.00
	CHECK / RECONNECT WIRING.		40.00	15.00
	TO SPRAY ANTI-RUST ON ACCIDENT AFFECTED PORTION.	NOT NECESSARY	120.00	-
	REMOVE / RENEW REAR EXHAUST SILENCER.		100.00	60.00
	REMOVE / REFIT REAR TAIL-GATE GLASS.	NOT NECESSARY	120.00	-

Report Ref No. CS/SPF22005319/Kqy3e2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE / REFIT REAR TAIL-GATE MECHANISM TO NEW DOOR.	NOT NECESSARY	100.00	-
	REMOVE / RENEW THE ABOVE PARTS INCLUDING KNOCKING, WELDING & CUTTING. INCLUSIVE OF THE REPAIR OF REAR TAIL-GATE AND REAR END PANEL.		1,000.00	400.00
			2,480.00	875.00
<b>GRAND TOTAL</b>			<b>6,205.76</b>	<b>2,012.84</b>

<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>1,600.00</b>
---	--	--	-----------------

Report Ref No. CS/SPF22005319/Kqy3e2

**NOTES : THE ESTIMATED UPPER RANGE OF REPAIR COST FOR THE DAMAGED VEHICLE IS IN THE REGION OF \$1,600.00-\$1,700.00**

**RECOMMENDED REPAIR DAYS: 4**

**WEEKEND: 0**

**TOTAL DAYS : 4**

**KONG SENG CHEONG**

**Licensed Appraiser**

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.