

Alan's United Auto Pte Ltd (Co.Reg.No:201113667N)

Blk 7 Sin Ming Industrial Estate, #01-76

Singapore 575642

Tel: 6453 8686 Fax: 6459 6550 Email: kennychan@alanutd.com;Janicechou@alanutd.com

RE  
R€  
Part  
Part  
Lab  
Prim  
Vali  
Fur

INSURER: **ERGO Insurance Pte. Ltd. (HQ)**

**PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	022092
Policy No:	DMPG21008036	Date of Loss:	01/06/2022
Vehicle Reg. No.:	<b>SLR5959P</b>	Driveable?	
Driver Age/Info:	32 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	GOH TRANSPORT SERVICES CO.PTE LTD		
Driver:	GOH HONG CHEN (WU FENGCHEN)		

Es  
No.

1  
2  
3  
4  
5  
6  
7  
8  
9  
10  
11  
12  
13  
14  
15  
16  
17  
18  
19  
20  
21  
22

Make/Model:	TOYOTA HARRIER, 2.0 ELEGANCE (A)	Vehicle Reg. Date:	27/07/2017
Vehicle Colour:	BROWN		
Engine No:	3ZRB788378	Chassis No:	ZSU600078991
Odometer:	0 KM		

*Not Authorized  
11 Day @  
Recovery After Paint  
Ex & Food*

Paint Type:  
Total Loss? **NO**  
Est. Duration of Repair (day) 10 ✓

Present Location: ALAN'S UNITED AUTO PTE LTD (HQ)

**COST OF CLAIMS**

	Amount
Parts	15,370.30
Miscellaneous Items	0.00
Labour	3,080.00
Paintwork Labour	0.00
Towing	0.00
<b>Gross Total (S\$)</b>	<b>18,450.30</b>
<b>+ GST 7.00% (S\$)</b>	<b>1,291.52</b>
<b>Nett Amount (S\$)</b>	<b>19,741.82</b>

This claim is handled by: **CHAN YEW SIAH**

401m  
402m  
45m  
7

# REPAIR DETAILS

## Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 03 Jun 2022)  
 Parts: M1-SUV TOYOTA HARRIER 2.0 Elegance (A) (Catalogue:Merimen Singapore 1.0)  
 Labour: Repairer's (Price-denominated Standard List)  
 Print Code: Alan's United Auto Pte Ltd/SLR5959P/03/06/2022 16:44  
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page  
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

## Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount		
1	1		*FRONT WINDSCREEN GLASS	CM	0.00	0.00	*900.00 F	L
2	1		*FRONT W/S GLASS RH CORNER GARNISH	DIS	0.00	0.00	*50.00 F	
3	1		*FRONT W/S GLASS MOULDING	M	0.00	0.00	*125.00 F	
4	1		*FRONT WIPER GARNISH	DL	0.00	0.00	*240.00 F	
5	1		*BONNET	R	0.00	0.00	*490.00 F	
6	1		*BONNET INSULATOR	R	0.00	0.00	*280.00 F	X
7	1		*BONNET CHROME	MIT	0.00	0.00	*180.00 F	C
8	2		*BONNET HINGE	R	0.00	0.00	*140.00 F	X
9	2		*BONNET DAMPER		0.00	0.00	*380.00 F	
10	1		*BONNET INNER LOCK	DIS	0.00	0.00	*95.00 F	
11	1		*FRONT SUPPORT PANEL		0.00	0.00	*420.00 F	
12	1		*SUPPORT PANLE TOP COVER	DL	0.00	0.00	*210.00 F	
13	12		*SUPPORT PANEL TOP COVER CLIP	M	0.00	0.00	*24.00 F	
14	2		*SUPPORT PANEL SIDE PANEL	DIS R	0.00	0.00	*156.00 F	L
15	2		*SIDE SUPPORT PANEL SIDE PANEL	DIS R	0.00	0.00	*120.00 F	L
16	2		*SUPPORT PANEL SIDE GUIDE -TOP	DIS R	0.00	0.00	*110.00 F	L
17	2		*SUPPORT PANEL SIDE GUIDE -LOWER	DIS	0.00	0.00	*90.00 F	
18	2		*HEADLAMP ASSY	DIS CM NIS MZ CM	0.00	0.00	*2,400.00 F	L
19	2		*HEADLAMP TOP PANEL	DIS R	0.00	0.00	*240.00 F	L
20	1		*RADIATOR ASSY		0.00	0.00	*600.00 F	
21	1		*RADIATOR FAN COWLING		0.00	0.00	*140.00 F	
22	1		*RADIATOR TOP COVER		0.00	0.00	*85.00 F	
23	1		*RADIATOR SPARE TANK	R	0.00	0.00	*160.00 F	X
24	1		*AIR CON CONDENSER (OEM)		0.00	0.00	*380.00 F	
25	1		*AIR CON DISCHARGE PIPE		0.00	0.00	*210.00 F	
26	1		*AIR CON SUCTION HOSE		0.00	0.00	*270.00 F	
27	1		*AIR CON LIQUID PIPE		0.00	0.00	*320.00 F	
28	1		*FRONT GRILLE	CM	0.00	0.00	*280.00 F	L
29	1		*FRONT BUMPER FASCIA	R	0.00	0.00	*340.00 F	L
30	2		*FRONT BUMPER SIDE RETAINER	CM/DIS	0.00	0.00	*150.00 F	
31	1		*FRONT BUMPER REINFORCEMENT	R	0.00	0.00	*220.00 F	
32	1		*FRONT BUMPER SPONGE (CTR)	CM	0.00	0.00	*90.00 F	
33	1		*FRONT BUMPER LOWER GRILLE	M	0.00	0.00	*170.00 F	
34	1		*FRONT BUMPER TOP BEAM	R	0.00	0.00	*180.00 F	
35	2		*FRONT BUMPER SIDE BEAM	DIS R	0.00	0.00	*220.00 F	L
36	2		*FRONT BUMPER SIDE SPONGE	DIS CM	0.00	0.00	*110.00 F	L
37	1		*FRONT BUMPER RH TOWING COVER	MIT	0.00	0.00	*28.00 F	
38	1		*FRONT BUMPER UNDER COVER	R	0.00	0.00	*170.00 F	X
39	2		*FRONT RH DOOR HINGE	R	0.00	0.00	*90.00 F	X
40	1		*FRONT RH BUMPER FOGLAMP		0.00	0.00	*135.00 F	
41	1		*FRONT RH BUMPER FOGLAMP COVER		0.00	0.00	*60.00 F	
42	1		*FRONT RH FENDER	RUC	0.00	0.00	*480.00 F	
43	1		*FRONT RH FENDER INNER SHIELD	DIS	0.00	0.00	*190.00 F	
44	1		*FRONT RH FENDER TOP GARNISH	DIS	0.00	0.00	*115.00 F	
45	1		*TAIL GATE	R	0.00	0.00	*600.00 F	

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
46	2		*TAIL GATE GLASS SIDE MOULDING	<i>Ne</i> 0.00	0.00	*70.00 F	✓
47	1		*TAIL GATE HARRIER EMBLEM	<i>Ne</i> 0.00	0.00	*45.00 F	✓
48	1		*REAR BUMPER FASCIA	<i>Ne/Ad</i> 0.00	0.00	*580.00 F	✓
49	1		*REAR BUMPER LOWER SPOILER	<i>Ad</i> 0.00	0.00	*240.00 F	✓
50	1		*REAR LH BUMPER SIDE RETAINER	<i>DIT</i> 0.00	0.00	*45.00 F	✓
51	1		*FRONT W/S GLASS SEALANT	<i>Ne</i> 0	0.00	*60.00 FS	<i>40W</i>
52	1		*ERP IU BRACKET	0	0.00	*25.00 FS	✓
53	1		*REAR W/S GLASS SEALANT	<i>Ne</i> 0	0.00	*60.00 FS	<i>40W</i>
54	1		*FRONT NO.PLATE WITH BOX	0	0.00	*50.00 FS	<i>45W</i>
55	1		*FRONT W/S GLASS SOLAR FILM	<i>In kind ??</i> 0	0.00	*350.00 FS	<i>?</i>
56	1		*RADIATOR COOLANT	0	0.00	*30.00 FS	✓
57	1		*FRONT BUMPER CLIP (SET)	0	0.00	*30.00 FS	✓

F=Franchise part. S=SpcNett.

Sub Total (S\$) **14,028.00**  
 + Margin on L,N Items 10.00% (S\$) **1,342.30**  


---

**Total Parts (S\$) 15,370.30**

Alan's United Auto Pte Ltd/SLR5959P/03/06/2022 16:44. Not valid without Reference section.  
 Generated using Merimen e-Claims IEAS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

# Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

## Estimates on Labour

No	Particulars	Lab.Type	Amount
<b>Labour Items</b>			
1	TO REWIRE DAMAGED PARTS AND REFOCUS HEADLAMP BEAM	New	60.00 <i>201</i>
2	TO REMOVE AIR CON CONDENSER ,PIPES,DRIER,VACUUM AIR CON SYSTEM & RECHARGE GAS	New	120.00 <i>1001</i>
3	TO REMOVE & RENEW FRONT W/S GLASS AND CONDUCT WATER LEAK TEST	New	150.00 <i>1201</i>
4	TO REMOVE & REFIX REAR W/S GLASS AND CONDUCT WATER LEAK TEST	New	150.00 <i>1201</i>
5	TO PUTTY AND SPRAY REPLACED PARTS	New	1,400.00 <i>12001</i>
6	TO REMOVE ,CUT OUT DAMAGED PARTS,PANEL BEATING,WELDING,ALIGN,REFIX AND TO RENEW ABOVE PARTS	New	1,200.00 <i>10001</i>
<b>Gross Labour Cost (S\$)</b>			<b>3,080.00</b>

Alan's United Auto Pte Ltd/SLR5959P/03/06/2022 16:44. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >