

ASS. REC. BY:

REF:

EGE / 220053271kv

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. DMPG21008036

Claims No. CDMPG22001057


Sum Insured: _____ Excess: 7000

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \$100k

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 10 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SUR 5959P Yr Regn: 07, 17

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make: Toy Harrier c.c. 1986

Colour: h. Black A/C: Insured / Std / NI / NA

Sp. Reading: 106P72 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: ZSU60 0078991

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: NII / S/Rim / STD / Rim or

Tyre Size: F: 225/65R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front _____ Rear _____

R/Bal. 5 mm R/Bal. 6 mm

L/Bal. 5 mm L/Bal. 6 mm

D.O.A. 1/6/22 D.O.I. 6/6/2022

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Rear O/S & Rear N/S

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
/	Check Sole film insured or not??
24/6	UIC by 8/12, 2001 Confirmed (red 6250.30, 34%)

Date/Time, File Pass to?

: Prel. Report

: Final Report

1)

Date/Time, File Return to?

2) 24/6/22-typist

Days Of Repair: 10

Resurvey No. of Trlp: 2

Survey Fee:

Transportation:

\$ - RS. \$

Excess

Others

TOTAL

Add Fee: : Site Insp (\$)

: Interview (\$)

: Tech Invs (\$)

: Weekend (\$)

Report Format: merimen

Lump Sum H.B.t: (\$ 12,200)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	033N
Vehicle Details	
Vehicle No.:	SLR5959P
Vehicle to be Exported:	Yes
Intended Deregistration Date:	03 Jun 2022
Vehicle Make:	TOYOTA
Vehicle Model:	HARRIER ELEGANCE 2.0 A
Primary Colour:	Brown
Manufacturing Year:	2016
Engine No.:	3ZRB788378
Chassis No.:	ZSU600078991
Maximum Power Output:	111.0 kW (148 bhp)
Open Market Value:	\$28,742.00
Original Registration Date:	27 Jul 2017
First Registration Date:	27 Jul 2017
Transfer Count:	1
Actual ARF Paid:	\$27,239.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Jul 2027
PARF Rebate Amount:	\$20,429.00
Intended COE Rebate Details	
COE Expiry Date:	26 Jul 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$47,501.00
COE Rebate Amount:	\$24,440.00
Total Rebate Amount:	\$44,869.00

The information contained herein is correct as at 02 Jun 2022

OK

Alan's United Auto Pte Ltd (Co.Reg.No:201113667N)

Blk 7 Sin Ming Industrial Estate, #01-76

Singapore 575642

Tel: 6453 8686 Fax: 6459 6550 Email: kennychan@alanutd.com;Janicechou@alanutd.com

INSURER: **ERGO Insurance Pte. Ltd. (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	022092
Policy No:	DMPG21008036	Date of Loss:	01/06/2022
Vehicle Reg. No.:	SLR5959P	Driveable?	
Driver Age/Info:	32 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	GOH TRANSPORT SERVICES CO.PTE LTD		
Driver:	GOH HONG CHEN (WU FENGCHEN)		

Make/Model:	TOYOTA HARRIER, 2.0 ELEGANCE (A)	Vehicle Reg. Date:	27/07/2017
Vehicle Colour:	BROWN	Chassis No:	ZSU600078991
Engine No:	3ZRB788378		
Odometer:	0 KM		
Paint Type:			<i>Not Authorized</i>
Total Loss?	NO		<i>11 Day @</i>
Est. Duration of Repair (day)	10 ✓		<i>Recovery After Paint Ex @ 700k</i>

Present Location: ALAN'S UNITED AUTO PTE LTD (HQ)

COST OF CLAIMS

	Amount
Parts	15,370.30
Miscellaneous Items	0.00
Labour	3,080.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	18,450.30
+ GST 7.00% (S\$)	1,291.52
Nett Amount (S\$)	19,741.82

This claim is handled by: **CHAN YEW SIAH**

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 03 Jun 2022)

Parts: M1-SUV TOYOTA HARRIER 2.0 Elegance (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Alan's United Auto Pte Ltd/SLR5959P/03/06/2022 16:44

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount		
1	1		*FRONT WINDSCREEN GLASS	CM	0.00	0.00	*900.00 F	✓
2	1		*FRONT W/S GLASS RH CORNER GARNISH	DIY	0.00	0.00	*50.00 F	✓
3	1		*FRONT W/S GLASS MOULDING	M	0.00	0.00	*125.00 F	✓
4	1		*FRONT WIPER GARNISH	DIY	0.00	0.00	*240.00 F	✓
5	1		*BONNET	R	0.00	0.00	*490.00 F	✓
6	1		*BONNET INSULATOR	Sn	0.00	0.00	*280.00 F	x
7	1		*BONNET CHROME	MIT	0.00	0.00	*180.00 F	✓
8	2		*BONNET HINGE	R	0.00	0.00	*140.00 F	✓
9	2		*BONNET DAMPER	R	0.00	0.00	*380.00 F	✓
10	1		*BONNET INNER LOCK	DIY	0.00	0.00	*95.00 F	✓
11	1		*FRONT SUPPORT PANEL	R	0.00	0.00	*420.00 F	✓
12	1		*SUPPORT PANLE TOP COVER	DIY	0.00	0.00	*210.00 F	✓
13	12		*SUPPORT PANEL TOP COVER CLIP	M	0.00	0.00	*24.00 F	✓
14	2		*SUPPORT PANEL SIDE PANEL	R	0.00	0.00	*156.00 F	x
15	2		*SIDE SUPPORT PANEL SIDE PANEL	MIS DIY	0.00	0.00	*120.00 F	✓
16	2		*SUPPORT PANEL SIDE GUIDE -TOP	DIY R	0.00	0.00	*110.00 F	4
17	2		*SUPPORT PANEL SIDE GUIDE -LOWER	DIY	0.00	0.00	*90.00 F	✓
18	2		*HEADLAMP ASSY	DIY CM	0.00	0.00	*2,400.00 F	✓
19	2		*HEADLAMP TOP PANEL	DIY R	0.00	0.00	*240.00 F	✓
20	1		*RADIATOR ASSY	R	0.00	0.00	*600.00 F	✓
21	1		*RADIATOR FAN COWLING	CM	0.00	0.00	*140.00 F	✓
22	1		*RADIATOR TOP COVER	CM	0.00	0.00	*85.00 F	✓
23	1		*RADIATOR SPARE TANK	Sn	0.00	0.00	*160.00 F	x
24	1		*AIR CON CONDENSER (OEM)	R	0.00	0.00	*380.00 F	✓
25	1		*AIR CON DISCHARGE PIPE		0.00	0.00	*210.00 F	x
26	1		*AIR CON SUCTION HOSE		0.00	0.00	*270.00 F	x
27	1		*AIR CON LIQUID PIPE		0.00	0.00	*320.00 F	x
28	1		*FRONT GRILLE	CM	0.00	0.00	*280.00 F	✓
29	1		*FRONT BUMPER FASCIA	R	0.00	0.00	*340.00 F	✓
30	2		*FRONT BUMPER SIDE RETAINER	CM/DIY	0.00	0.00	*150.00 F	✓
31	1		*FRONT BUMPER REINFORCEMENT	R	0.00	0.00	*220.00 F	✓
32	1		*FRONT BUMPER SPONGE (CTR)	CM	0.00	0.00	*90.00 F	✓
33	1		*FRONT BUMPER LOWER GRILLE	DIY	0.00	0.00	*170.00 F	✓
34	1		*FRONT BUMPER TOP BEAM	R	0.00	0.00	*180.00 F	✓
35	2		*FRONT BUMPER SIDE BEAM	DIY R	0.00	0.00	*220.00 F	4
36	2		*FRONT BUMPER SIDE SPONGE	DIY CM	0.00	0.00	*110.00 F	4
37	1		*FRONT BUMPER RH TOWING COVER	MIT	0.00	0.00	*28.00 F	✓
38	1		*FRONT BUMPER UNDER COVER	Sn	0.00	0.00	*170.00 F	x
39	2		*FRONT RH DOOR HINGE	R	0.00	0.00	*90.00 F	x
40	1		*FRONT RH BUMPER FOGLAMP	MIS CM	0.00	0.00	*135.00 F	✓
41	1		*FRONT RH BUMPER FOGLAMP COVER	DIY	0.00	0.00	*60.00 F	✓
42	1		*FRONT RH FENDER	R	0.00	0.00	*480.00 F	✓
43	1		*FRONT RH FENDER INNER SHIELD	DIY	0.00	0.00	*190.00 F	✓
44	1		*FRONT RH FENDER TOP GARNISH	DIY	0.00	0.00	*115.00 F	✓
45	1		*TAIL GATE	R	0.00	0.00	*600.00 F	✓

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
46	2		*TAIL GATE GLASS SIDE MOULDING	<i>Ne</i> 0.00	0.00	*70.00 F ✓
47	1		*TAIL GATE HARRIER EMBLEM	<i>Ne</i> 0.00	0.00	*45.00 F ✓
48	1		*REAR BUMPER FASCIA	<i>Bu/Red</i> 0.00	0.00	*580.00 F ✓
49	1		*REAR BUMPER LOWER SPOILER	<i>Ad</i> 0.00	0.00	*240.00 F ✓
50	1		*REAR LH BUMPER SIDE RETAINER	<i>DIT</i> 0.00	0.00	*45.00 F ✓
51	1		*FRONT W/S GLASS SEALANT	<i>Ne</i> 0	0.00	*60.00 FS <i>401a</i> ✓
52	1		*ERP IU BRACKET	0	0.00	<i>Ne</i> *25.00 FS ✓
53	1		*REAR W/S GLASS SEALANT	<i>Ne</i> 0	0.00	*60.00 FS <i>401a</i> ✓
54	1		*FRONT NO.PLATE WITH BOX	0	0.00	<i>By</i> *50.00 FS <i>451a</i> ✓
55	1		*FRONT W/S GLASS SOLAR FILM	<i>In Road ??</i> 0	0.00	<i>NZ</i> *350.00 FS ✓
56	1		*RADIATOR COOLANT	0	0.00	<i>Ne</i> *30.00 FS ✓
57	1		*FRONT BUMPER CLIP (SET)	0	0.00	<i>Ne</i> *30.00 FS ✓

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	14,028.00
+ Margin on L,N Items 10.00% (\$\$)	1,342.30
Total Parts (\$\$)	15,370.30

Alan's United Auto Pte Ltd/SLR5959P/03/06/2022 16:44. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			<i>201</i>
1	TO REWIRE DAMAGED PARTS AND REFOCUS HEADLAMP BEAM	New	60.00
2	TO REMOVE AIR CON CONDENSER ,PIPES,DRIER,VACUUM AIR CON SYSTEM & RECHARGE GAS	New	<i>1001</i> 120.00
3	TO REMOVE & RENEW FRONT W/S GLASS AND CONDUCT WATER LEAK TEST	New	<i>1201</i> 150.00
4	TO REMOVE & REFIX REAR W/S GLASS AND CONDUCT WATER LEAK TEST	New	<i>1201</i> 150.00
5	TO PUTTY AND SPRAY REPLACED PARTS	New	1,400.00 <i>12001</i>
6	TO REMOVE ,CUT OUT DAMAGED PARTS,PANEL BEATING,WELDING,ALIGN,REFIX AND TO RENEW ABOVE PARTS	New	1,200.00 <i>1001</i>
Gross Labour Cost (\$\$)			3,080.00

Alan's United Auto Pte Ltd/SLR5959P/03/06/2022 16:44. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >