

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III22005328/RPA3Q2**Date:** 10/01/2023REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D20MPC0005613_01
Claimant Vehicle No : SHD6313S **Insured Vehicle No :** SJT3730H
 Date of Loss: 01/06/2022 Nature of Claim: TP Claim No: MPC2022D0002994

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHD6313S**
 Make & Model: TOYOTA PRIUS, 1.8 HYBRID CVT (A) Engine No: 2ZRS100078
 Reg. Date: 01/11/2017 (Man. Year: 2017) Chassis No: JTDKB3FU403573299
 Colour: Maroon Odometer: 55327 km
 Engine Capacity: 1798 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
 Front Left Side: Sailun 6 mm Rear Left Side: Sailun 6 mm
 Front Right Side: Sailun 6 mm Rear Right Side: Sailun 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,986.80	2,725.57	10,261.23	79.01
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,472.00	720.00	1,752.00	70.87
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,458.80	3,445.57	12,013.23	77.71
Approved Total (Overridden) (S\$)		2,900.00		
Nett Amount (S\$)	15,458.80	2,900.00	12,558.80	81.24
+ Loss of Use (5.0 x S\$40.00/day) (S\$)		200.00		
+ Car Rental (5.0 x S\$103.26/day) (S\$)		516.30		
+ Doc/Search Fee (S\$)		7.00		
Nett Liability (S\$)		3,623.30		
Global Sum Settlement (S\$)		3,620.00		

INSPECTION

Date of Assignment: 03/06/2022
 Date Inspected: 03/06/2022 Inspected At: Strides Automotive Services Pte Ltd (Woodlands)
 60 Woodlands Industrial Park E4
 Singapore 757705
 Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 Aug 2022)
Parts:	144	TOYOTA PRIUS 1.8 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHD6313S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER ,FR BUMPER (DISC 25%)	Scratched	495.50 F	*371.63 F
2	1		*EMBLEM SIDE PANEL (HYBRID) (DISC 25%)	Necessary	52.90 F	*39.68 F
3	1		*UNIT HEADLAMP RH (DISC 10%)	Cracked	2,558.90 F	*2,303.01 F
4	1		*CLIPS PIECE ,FRT & RR BUMPER (DISC 25%) (10 PCS)	Necessary	15.00 F	*11.25 F
5	1		*UNIT HEADLAMP RH	Not Necessary	2,558.90 F	*- F
6	1		*LAMP ASSY ,FOG, RH	Not Necessary	910.20 F	*- F
7	1		*REINFORCEMENT FRONT UPPER	Not Necessary	691.10 F	*- F
8	1		*NUMBER PLATE	Not Necessary	35.00 F	*- F
9	1		*COVER ,FR BUMPER RH	Not Necessary	28.10 F	*- F
10	1		*COVER ,FR BUMPER LH	Not Necessary	28.10 F	*- F
11	1		*BRACKET ,FR BUMPER	Not Necessary	99.80 F	*- F
12	1		*ABSORBER ,FR BUMPER	Not Necessary	70.30 F	*- F
13	1		*EXTENSION SUB-ASSY ,LH	Not Necessary	116.30 F	*- F
14	1		*EXTENSION SUB-ASSY ,RH	Not Necessary	116.30 F	*- F
15	1		*REINFORCEMENT FRONT LOWER	Not Necessary	238.50 F	*- F
16	1		*ABSORBER ,FR BUMPER LOWER	Not Necessary	117.00 F	*- F
17	1		*SEAL ,HOOD TO FR END	Not Necessary	24.40 F	*- F
18	1		*EMBLEM ASSY FRONT	Not Necessary	87.10 F	*- F
19	1		*GRILLE ,RADIATOR	Not Necessary	165.00 F	*- F
20	1		*GRILLE SUB-ASSY	Not Necessary	335.60 F	*- F
21	2		*RETAINER ,FR BUMPER ,LH & RH	Not Necessary	8.50 F	*- F
22	1		*COVER ,ENGINE UNDER SIDE RH	Not Necessary	76.90 F	*- F
23	1		*LINER ,FR FENDER ,RH	Not Necessary	198.40 F	*- F
24	1		*PAD ,FR WHEEL RH	Not Necessary	57.70 F	*- F
25	1		*SEAL SUB-ASSY RH	Not Necessary	50.20 F	*- F
26	1		*PROTECTOR FR FENDER RH	Not Necessary	90.40 F	*- F
27	1		*WHEEL DISC FRONT	Not Necessary	1,555.10 F	*- F
28	1		*SUPPORT S/A RH	Not Necessary	237.00 F	*- F
29	1		*SUPPORT ,FR BUMPER RH	Not Necessary	76.90 F	*- F
30	1		*SUPPORT ,FR BUMPER LH	Not Necessary	82.30 F	*- F
31	1		*NUMBER PLATE FRAME	Not Necessary	25.00 F	*- F
32	1		*COMPUTER SUB-ASSY HEADLAMP RH NO.1	Not Necessary	486.40 F	*- F
33	1		*SUPPORT S/A UPPER	Not Necessary	364.90 F	*- F
34	1		*FENDER SUB-ASSY ,FR RH	Repair	933.10 F	*- F

F=Franchise part.

Total Parts (\$\$) **12,986.80** **2,725.57**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING & BODY WORK	New	676.00	300.00
2	SPRAY PAINT	New	1,296.00	400.00
3	TO DO WHEEL ALIGNMENT /TYRE BALANCING	New	120.00	0.00
4	TO WASH AND VACUUM	New	60.00	0.00
5	TO CHECK WIRING AND SYSTEM FUNCTION	New	120.00	20.00
6	TO APPLY RUST -PROOFING ON AFFECTED AREA	New	100.00	0.00
7	TO REPLACE SUNDRY PARTS	New	100.00	0.00
Gross Labour Cost (S\$)			2,472.00	720.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >