

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG22005330/TVY3E2**Date:** 13/04/2023REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	30001959671
Claimant Vehicle No :	GBC6198J	Insured Vehicle No :	SLG8469A
Date of Loss:	02/06/2022	Nature of Claim:	TP
		Claim No:	275812

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBC6198J		
Make & Model:	NISSAN NV200, 1.5 L MT ABS AIRBAG 2WD 6DR (M)	Engine No:	K9KF276D126764
Reg. Date:	09/04/2013 (Man. Year: 2011)	Chassis No:	VSKYBAM20U0033525
Colour:	Silver	Odometer:	0 km
Engine Capacity:	1461 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	175/70 R14	Rear Tyre Size:	175/70 R14
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,089.20	3,842.98	6,246.22	61.91
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,030.00	1,370.00	2,660.00	66.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,119.20	5,212.98	8,906.22	63.08
Approved Total (Overridden) (S\$)		4,150.00		
(S\$)	14,119.20	4,150.00	9,969.20	70.61
+ GST 8.00/8.00% (S\$)	1,129.54	332.00	797.54	70.61
Nett Amount (S\$)	15,248.74	4,482.00	10,766.74	70.61

INSPECTION

Date of Assignment:	06/06/2022	
Date Inspected:	07/06/2022 Inspected At:	Xin Yun Auto Pte Ltd (HQ) BLK 8 KAKI BUKIT AVE 4 #05-23 PREMIER @KAKI BUKIT Singapore 415675
Estimated Period of Repair:	5.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 10 Apr 2023)	
Parts:	N/A	NISSAN NV200 1.5 L MT ABS AIRBAG 2WD 6DR (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBC6198J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER ASSY	Dented	780.00 F	*780.00 FL
2	1		*REAR BUMPER LEFT BRACKET	No such part	98.00 F	*- FL
3	1		*REAR BUMPER RIGHT BRACKET	Serviceable	98.00 F	*- FL
4	1		*REAR BUMPER LEFT RETAINER	Cracked	85.00 F	*85.00 FL
5	1		*REAR BUMPER RIGHT RETAINER	Serviceable	85.00 F	*- FL
6	1		*REAR BUMPER TOW COVER	No such part	78.00 F	*- FL
7	1		*REINFORCEMENT SPONGE	Torn	280.00 F	*280.00 FL
8	1		*REAR BOOT - TAILGATE	Buckled	1,800.00 F	*1,800.00 FL
9	1		*REAR TAILGATE RUBBER GARNISH	Dented	372.20 F	*372.20 FL
10	1		*TAILGATE INTERNAL TRIM COVER	Serviceable	385.00 F	*- FL
11	1		*TAILGATE LOGO NISSAN	Necessary	95.00 F	*95.00 FL
12	1		*TAILGATE HOLDER / PULL POCKET	No such part	95.00 F	*- FL
13	1		*REAR TAILGATE EMBLEM / MODEL	Necessary	105.00 F	*105.00 FL
14	1		*REAR BOOT LOCK MECHANISM	Serviceable	280.00 F	*- FL
15	1		*REAR BOOT LOCK HOLDER	Not Necessary	95.00 F	*- FL
16	1		*REAR END TOP COVER	Cut	375.00 F	*375.00 FL
17	1		*ANTENNA, ELECTRICAL KEY	No such part	88.00 F	*- FL
18	2		*REAR TAILGATE NO PLATE LAMP	Not Necessary	65.00 F	*- FL
19	1		*REAR LEFT TAILLAMP	Not Necessary	550.00 F	*- FL
20	1		*REAR RIGHT TAILLAMP	Not Necessary	550.00 F	*- FL
21	1		*REAR LEFT CORNER LIGHT	No such part	250.00 F	*- FL
22	1		*REAR RIGHT CORNER LIGHT	No such part	250.00 F	*- FL
23	1		*REAR END LOWER TRAY	Not Necessary	350.00 F	*- FL
24	2		*WINDSCREEN RUBBER	No such part	280.00 F	*- FL
25	1		*REAR END PANEL	Repair	900.00 F	*- FL
26	10		*REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
27	1		*REAR END LOWER PANEL TOP GARNISH CLIPS (6PCS)	Necessary	50.00 FS	*20.00 FS
28	1		*REAR END LOWER PANEL SEALANT	Not Necessary	120.00 FS	*- FS
29	8		*REAR TAILGATE INNER TRIM BOARD CLIPS	Necessary	50.00 FS	*20.00 FS
30	1		*REAR TAILGATE OUTER GARNISH CLIPS (6PCS)	Necessary	50.00 FS	*20.00 FS
31	1		*REAR FLOOR PANEL SEALANT	Not Necessary	120.00 FS	*- FS
32	1		*REAR WINDSCREEN GLASS SEALANT	Necessary	80.00 FS	*50.00 FS
33	3		*REAR WINDSCREEN MOUNDING	No such part	320.00 FS	*- FS
34	2		*REAR BUMPER REVERSE SENSOR	Cracked	250.00 FS	*200.00 FS
35	1		*REAR NO PLATE WITH GARNISH	Not Necessary	80.00 FS	*- FS
36	2		*REVERSE SENSOR	Repeated	500.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 10,089.20 4,232.20
- List Item Discount on L Items 0.00/10.00% (\$\$) 0.00 389.22

Total Parts (\$\$) 10,089.20 3,842.98

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN REAR AFFECTED AREA AND REPLACE REAR DAMAGED PARTS, MAIN BODY FRAME RR FRAME DAMAGED	New	1,500.00	500.00
2	TO PUTTY AND SPRAY PAINTING REAR PORTION, BOOT INSIDE OUT, BUMPER, RIGHT FENDER DENT, MAIN FRAME METAL, REAR END PANEL, GUTTER SIDE PANEL FOR LEFT AND RIGHT	New	1,500.00	600.00
3	TO CHECK REAR LIGHTING AND WIRING	New	60.00	30.00
4	TO REMOVE AND INSTALL REAR TAILGATE LOCK MECHANISM	New	80.00	50.00
5	TO REMOVE & INSTALL REAR WINDSCREEN GLASS TO FACILITATE THE REPAIR	New	150.00	80.00
6	TO APPLY ANTI RUST PROOFING TO REAR AFFECTED AREA INCLUDING BEHIND SPARE TYRE AREA	New	250.00	50.00
7	TO REMOVE AND INSTALL REAR BUMPER REVERSE SENSOR	New	80.00	30.00
8	TO REMOVE AND INSTALL REAR EXHAUST MUFFLER ASSY	New	250.00	0.00
9	TO REMOVE AND REAR INTERAL INTERNAL TRIMS TO FACILITATE THE REPAIR	New	80.00	30.00
10	TO REMOVE AND INSTALL REAR CAMERA TO FACILITATE THE REPAIR	New	80.00	0.00
Gross Labour Cost (S\$)			4,030.00	1,370.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >