



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJU 258U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	DISTORTED	1,280.00	900.00
2	REAR BUMPER RETAINER @\$58.00	NECESSARY	116.00	116.00
1	REAR BUMPER DIFFUSER	SCRATCHED	385.00	385.00
1	REAR RIGHT WHEEL TRIM PROTECTOR	DISTORTED	358.00	358.00
	LESS 10% DISCOUNT		-213.90	-175.90
			1,925.10	1,583.10
<u>SPECIAL NETT ITEMS</u>				
1	SET REAR BUMPER CLIP (SN)	NECESSARY	30.00	30.00
2	REAR BUMPER PDC SENSOR @\$100.00 (SN)	CUT	200.00	200.00
			230.00	230.00
<u>LABOUR</u>				
	DIAGNOSE ,REPAIR TO RECTIFY ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		120.00	30.00
	TO PROVIDE WORKMANSHIP LABOUR TO REMOVE DAMAGE PARTS FOR ASSESSMENT AT TO NEW BODYPARTS ,REPAIR ,RE-CONSTRUCT AND READJUST STRUCTURE BODY ALIGNMENTS AND DAMAGED CONSISTENT FROM THE ACCIDENT.		800.00	300.00
	TO RESPRAY PAINTING FOR CHARGE BODYPARTS ,REPAIR PORTION AND WHERE CONSISTENT FROM THE ACCIDENT.		800.00	300.00
			1,720.00	630.00
GRAND TOTAL			3,875.10	2,443.10
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,950.00

Report Ref No. CS/AGI22005331/Vvy3q2

THEVAN THOMAS KARTHIKESAVAN

Asst. Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.