

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22005333/KVY3Q2**Date:** 03/11/2022REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNA00255832101

Claimant Vehicle No : SLR2068E **Insured Vehicle No :** SLU6466Y

Date of Loss: 01/06/2022 Nature of Claim: TP Claim No: SNM22D203891/C02/CSC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLR2068E**

Make & Model: SUZUKI SWIFT, 1.6 MT (M) Engine No: M16A1389616

Reg. Date: 07/01/2009 (Man. Year: 2008) Chassis No: JSAEZC31S00202177

Colour: Metallic Dark Blue Odometer: 148577 km

Engine Capacity: 1586 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 205/45Z R16 Rear Tyre Size: 205/45Z R16

Front Left Side: Bridgestone 5 mm Rear Left Side: Dunlop 6 mm

Front Right Side: Bridgestone 5 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,684.35	2,537.39	146.96	5.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,160.00	660.00	500.00	43.10
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,844.35	3,197.39	646.96	16.83
Approved Total (Overridden) (S\$)		2,600.00		
(S\$)	3,844.35	2,600.00	1,244.35	32.37
+ GST 7.00/7.00% (S\$)	269.10	182.00	87.10	32.37
Nett Amount (S\$)	4,113.45	2,782.00	1,331.45	32.37

INSPECTION

Date of Assignment: 06/06/2022

Date Inspected: 08/06/2022 Inspected At: Ah Lim Motor Company (AMK)
10 Ang Mo Kio Industrial Park 2A, #01-09 AMK
Autopoint
Singapore 568047

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS**Reference**

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 02 Nov 2022)
Parts: 144	SUZUKI SWIFT 1.6 MT (M) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLR2068E)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled	769.50 FL	*769.50 FL
2	1		*REAR BUMPER LOWER GRILLE	Cracked	1,621.40 FL	*1,621.40 FL
3	1		*REAR BUMPER LOWER GRILLE CTR COVER	Missing	35.70 FL	*35.70 FL
4	2		*REAR BUMPER REINFORCEMENT BKT	Repair	56.10 FL	*- FL
5	2		*REAR BUMPER SIDE RETAINER LH & RH	Serviceable	50.00 FL	*- FL
6	4		*REAR BUMPER CLIPS	Necessary	20.00 FL	*20.00 FL
7	2		*REAR BUMPER NO PLATE LAMP LH & RH	Cracked (1 PCS ONLY)	53.60 FL	*26.80 FL
8	8		*REAR FENDER COWLING CLIPS	Not Necessary	40.00 FL	*- FL
9	1		*REAR VIEW CAMERA	Shorted	200.00 FS	*200.00 FS
10	1		*NUMBER PLATE	Cracked	35.00 FS	*35.00 FS
11	1		*SET REVERSE SENSOR	Shorted	200.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,081.30	2,908.40
- List Item Discount on L Items 15.00/15.00% (\$\$)	396.95	371.01
Total Parts (\$\$)	2,684.35	2,537.39

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING ,WIRE SOCKETS AND ETC TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS ,TEST AND RECTIFY FOR PROPER FUNCTIONING	New	40.00	10.00
2	TO REMOVE AND REINSTALL /REPLACE FRONT /REAR BUMPER SENSORS	New	60.00	50.00
3	TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS	New	60.00	0.00
4	TO DISMANTLE ALL DAMAGED PARTS TO CUT & WELD ,TO KNOCK & REPAIR REAR END PANEL INNER PANELS AND AFFECTED TO REFIT LISTED PARTS BACK SAME	New	500.00	300.00
5	TO SPRAY REAR BUMPER ,REAR END PANEL	New	500.00	300.00
			Gross Labour Cost (\$\$)	1,160.00
				660.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >