

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22005335/ANY3Q2**Date:** 05/10/2022**REFERENCE**Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSNA00086322100

Claimant Vehicle No : SJF9667S**Insured Vehicle No :** GBH3190Z

Date of Loss: 03/06/2022

Nature of Claim: TP

Claim No: SNM22D203925/C02/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SJF9667S**

Make & Model: KIA PICANTO, 1.1 (A)

Engine No: G4HG8430016

Reg. Date: 17/06/2008 (Man. Year: 2008)

Chassis No: KNABA24338T613687

Colour: Yellow

Odometer: 169009 km

Engine Capacity: 1086 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 175/65 R14

Rear Tyre Size: 175/65 R14

Front Left Side: Falken 6 mm

Rear Left Side: Falken 6 mm

Front Right Side: Falken 6 mm

Rear Right Side: Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,844.30	4,584.10	6,260.20	57.73
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,530.00	1,890.00	1,640.00	46.46
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	14,374.30	6,474.10	7,900.20	54.96
Approved Total (Overridden) (\$\$)		4,700.00		
Nett Amount (\$\$)	14,374.30	4,700.00	9,674.30	67.30

INSPECTION

Date of Assignment: 07/06/2022

Date Inspected: 06/06/2022 Inspected At:

HD Perfect Autowork Pte Ltd (HQ)
8 Kaki Bukit Ave 4, #08-09 Premier @ Kaki Bukit
Singapore 415875

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Sep 2022)
Parts:	144	KIA PICANTO 1.1 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJF9667S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAIL GATE	Dented	927.00 FL	*754.00 FL
2	2		*TAIL GATE STOPPER	Not Necessary	36.00 FL	*- FL
3	1		*TAIL GATE INNER TRIM BOARD	Not Necessary	238.00 FL	*- FL
4	1		*TAIL GATE OUTER HANDLE	Not Necessary	48.00 FL	*- FL
5	1		*TAIL GATE WEATHERSTRIP	Cut	196.00 FL	*196.00 FL
6	1		*TAIL GATE KEY LOCK	Not Necessary	189.00 FL	*- FL
7	1		*TAIL GATE INNER LOCK	Damaged	196.00 FL	*196.00 FL
8	1		*TAIL GATE INNER LOCK MOTOR	Not Necessary	187.00 FL	*- FL
9	1		*TAIL GATE LOGO GARNISH	Not Necessary	278.00 FL	*- FL
10	1		*TAIL GATE LOGO	Not Necessary	49.00 FL	*- FL
11	1		*TAIL GATE EMBLEM PICANTO	Necessary	52.00 FL	*52.00 FL
12	1		*TAIL GATE WINDSCREEN MOULDING	Necessary	124.00 FL	*124.00 FL
13	2		*REAR NUMBER PLATE LAMP	Not Necessary	60.00 FL	*- FL
14	2		*REAR FENDER INNER TRIM	Cracked	978.00 FL	*490.00 FL
15	2		*REAR FENDER SPLASHIELD	Torn	144.00 FL	*144.00 FL
16	1		*REAR LUGGAGE COVER	Not Necessary	210.00 FL	*- FL
17	1		*REAR BUMPER	Deformed	490.00 FL	*490.00 FL
18	2		*REAR BUMPER SIDE RETAINER	Necessary	96.00 FL	*96.00 FL
19	1		*REAR BUMPER REINFORCEMENT	Smashed	347.00 FL	*347.00 FL
20	2		*REAR TAIL LAMP	Cracked	796.00 FL	*540.00 FL
21	2		*REAR TAIL LAMP PANEL	Repair	680.00 FL	*- FL
22	2		*REAR TAIL LAMP INNER PANEL	Repair	786.00 FL	*- FL
23	1		*REAR END PANEL	Dented	497.00 FL	*497.00 FL
24	2		*REAR END PANEL AIR VENT	Deformed	116.00 FL	*116.00 FL
25	1		*REAR END PANEL TOP GARNISH	Deformed	187.00 FL	*187.00 FL
26	1		*REAR FLOOR PANEL TOP BOARD	Deformed	220.00 FL	*220.00 FL
27	1		*REAR FLOOR PANEL	Repair	890.00 FL	*- FL
28	1		*REAR FLOOR PANEL TOOLS BOX	Not Necessary	290.00 FL	*- FL
29	1		*REAR CHASSIS MEMBER LH	Not Necessary	920.00 FL	*- FL
30	1		*REAR NUMBER PLATE	Not Necessary	80.00 FS	*- FS
31	1		*SET REAR BUMPER CLIP	Necessary	60.00 FS	*30.00 FS
32	1		*SET TAIL LAMP CLIP	Necessary	60.00 FS	*20.00 FS
33	1		*TAIL LAMP PANEL SEALANT	Not Necessary	80.00 FS	*- FS
34	1		*TAIL GATE SEALANT	Not Necessary	80.00 FS	*- FS
35	1		*SET TAIL GATE INNER TRIM BOARD CLIP	Not Necessary	80.00 FS	*- FS
36	1		*SET TAIL GATE LOGO GARNISH CLIP	Not Necessary	40.00 FS	*- FS
37	1		*TAIL GATE WINDSCREEN INNER SHIELD	Not Necessary	80.00 FS	*- FS
38	1		*TAIL GATE WINDSCREEN SEALANT	Necessary	80.00 FS	*60.00 FS
39	1		*TAIL GATE EMBLEM CYCLE & CARRIAGE	Necessary	70.00 FS	*40.00 FS
40	1		*SET REAR FENDER SPLASHIELD CLIP	Necessary	60.00 FS	*40.00 FS
41	1		*SET REAR FENDER INNER TRIM CLIP	Necessary	80.00 FS	*60.00 FS
42	1		*SET REAR END PANEL TOP GARNISH CLIP	Necessary	60.00 FS	*10.00 FS
43	1		*REAR END PANEL INSULATION SEAL	Necessary	150.00 FS	*60.00 FS
44	1		*REAR FLOOR PANEL INSULATION SEAL	Not Necessary	180.00 FS	*- FS
45	1		*SET REVERSE SENSOR	Damaged	220.00 FS	*200.00 FS
46	1		*TRIANGLE BREAK DOWN SIGN	Deformed	180.00 FS	*60.00 FS

Report was unsubmitted during this print-out.

10/5/22, 10:00 AM

Adjuster Report

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					11,867.00	5,029.00
- List Item Discount on L Items 10.00/10.00% (S\$)					1,022.70	444.90
Total Parts (S\$)					10,844.30	4,584.10
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,REMOVAL AND REPLACING PARTS	New	1,500.00	800.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,200.00	800.00
3	TUFF COAT	New	150.00	60.00
4	WIRING CHECK	New	80.00	30.00
5	REMOVE AND REFIX REAR TAIL GATE WINDSCREEN	New	120.00	120.00
6	TRANFER TAILGATE MECHANISM	New	80.00	80.00
7	CONDUCT WATER LEAKAGE TEST	New	100.00	0.00
8	REMOVE AND REFIX REAR FUEL TANK	New	120.00	0.00
9	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC	New	180.00	0.00
Gross Labour Cost (\$\$)			3,530.00	1,890.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >