

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22005343/VQY3Q2**Date:** 10/11/2022REFERENCEHandling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMHCSNA00015132102

**Claimant Vehicle
No :** SGA1116E**Insured Vehicle
No :** SMP3688H

Date of Loss: 01/06/2022

Nature of Claim: TP

Claim
No: SNM22D203926/C02/TANKLDESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SGA1116E**Make & Model: MERCEDES-BENZ E200, 2.0 EXCLUSIVE (R18 LED)
(A)

Engine No: 26492030317833

Reg. Date: 08/07/2021 (Man. Year: 2020)

Chassis No: W1K2130802A889708

Colour: Grey

Odometer: 17677 km

Engine Capacity: 1991 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/45 R18

Rear Tyre Size: 245/45 R18

Front Left Side: Michelin 7 mm

Rear Left Side: Michelin 7 mm

Front Right Side: Michelin 7 mm

Rear Right Side: Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,110.50	679.50	1,431.00	67.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,230.00	480.00	750.00	60.98
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,340.50	1,159.50	2,181.00	65.29
Approved Total (Overridden) (S\$)		900.00		
Nett Amount (S\$)	3,340.50	900.00	2,440.50	73.06

INSPECTION

Date of Assignment: 06/06/2022

Date Inspected: 07/07/2022 Inspected At:

3023A UBI ROAD 1

#01-63

SINGAPORE 408717

Repairer: Sin Seng Hong Spray Painting &
Services (HQ)

Estimated Period of Repair: 2.0 days

Adjuster: Thevan Thomas Karthikesavan**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

Reference

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOOUR CHARGES TO REMOVE AND REPLACE ,TO CUT AND WELD ,TO KNOCK AND RESHAPE AFFECTED PARTS /AREAS	New	500.00	250.00
2	SPRAY PAINTING CHARGES TO PUTTY AND SPRAY ALL AFFECTED PARTS /AREAS	New	600.00	200.00
3	TO CHECK WIRING	New	40.00	30.00
4	TO RE-APPLY ANTI-RUST UNDERCOAT	New	90.00	0.00
Gross Labour Cost (S\$)			1,230.00	480.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >