

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/AIS22005346/EVY3Q2**Date:** 16/08/2022REFERENCE

Handling Insurer:	Allianz Insurance Singapore Pte. Ltd.	Policy No:	SP2000488242
Claimant Vehicle No :	SNF308R	Insured Vehicle No :	SME8690A
Date of Loss:	27/05/2022	Nature of Claim:	TP
		Claim No:	202222005075KC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNF308R	Engine No:	HIDDEN
Make & Model:	BMW X1, 1.5 SDRIVE 18I (A)	Chassis No:	WBY42DU030S391502
Reg. Date:	12/05/2022 (Man. Year: 2022)	Odometer:	3147 km
Colour:	Black		
Engine Capacity:	0 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	275/40 R20	Rear Tyre Size:	275/40 R20
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,406.10	935.20	2,470.90	72.54
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,667.00	2,004.00	663.00	24.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	6,073.10	2,939.20	3,133.90	51.60
+ GST 7.00/7.00% (S\$)	425.12	205.74	219.38	51.60
Nett Amount (S\$)	6,498.22	3,144.94	3,353.28	51.60

INSPECTION

Date of Assignment:	22/06/2022	Performance Motors Limited (Alexandra)
Date Inspected:	21/06/2022 Inspected At:	303 Alexandra Road, Sime Darby Performance Centre
Estimated Period of Repair:	3.0 days	Singapore 159941

Adjuster: CHEN TSUE YEE**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 16 Aug 2022)
Parts:	M1-SUV	BMW X1 1.5 SDRIVE 18l (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNF308R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	80.00 FS	*80.00 FS
2	10		*PLASTIC NUT FOR COARSE THREADED PIN	Not Necessary	8.50 FS	*- FS
3	10		*EXPANDING NUT L=19.9MM	Not Necessary	14.00 FS	*- FS
4	10		*C CLIP FOR PLASTIC NUT	Not Necessary	11.00 FS	*- FS
5	7		*PLASTIC NUT	Not Necessary	19.25 FS	*- FS
6	15		*EXPANDING RIVET	Not Necessary	7.50 FS	*- FS
7	1		*REAR BUMPER PANEL PRIMER (PDC+PMA)	Not Necessary	1,593.30 FS	*- FS
8	1		*REAR BUMPER BOTTOM TRIM PANEL (GLOS)	Dented	297.75 FS	*297.75 FS
9	1		*REAR BUMPER COVER PAINTED (FROZEN G)	Cut	274.35 FS	*274.35 FS
10	1		*ADAPTER FOR SUPPORT REAR	Broken	166.90 FS	*166.90 FS
11	1		*UNDERSHIELD	Not Necessary	102.20 FS	*- FS
12	1		*TORSION STRU	Not Necessary	43.05 FS	*- FS
13	1		*TORSION STRU	Not Necessary	48.25 FS	*- FS
14	6		*PLUG BLACK D=5MM	Not Necessary	5.70 FS	*- FS
15	1		*CONTROL UNIT	Not Necessary	514.25 FS	*- FS
16	1		*SENSOR LEAD SMART OPENER TOP	Not Necessary	51.95 FS	*- FS
17	1		*SENSOR LEAD SMART OPENER BOTTOM	Not Necessary	51.95 FS	*- FS
18	1		*UNDERBODY PANELLING REAR END	Broken	102.20 FS	*102.20 FS
19	10		*EXPANDING RIVET BLACK	Necessary	14.00 FS	*14.00 FS
					Total Parts (S\$)	3,406.10 935.20

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE REAR BUMPER	New	1,275.00	850.00
2	TO RESPRAY REAR BUMPER	New	1,038.00	986.00
3	TO CHECK ELECTRICAL WIRING SYSTEM	New	177.00	168.00
4	TO REMOVE OLD PDC ASSEMBLY ,REPLACE DAMAGED PARTS AND RECONNETC TO NEW BUMPER INCLUDING RE CONNET TO NEW BUMPER AND CONDUCT CHECK FOR PROPER FUNCTION	New	177.00	0.00
Gross Labour Cost (S\$)			2,667.00	2,004.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >