

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22005348/RVY3M4**Date:** 28/07/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNA00243562104

Claimant Vehicle No : SMU6329Z **Insured Vehicle No :** SLU707S

Date of Loss: 31/05/2022 Nature of Claim: TP Claim No: SNM22D203896/C02/TANKW

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMU6329Z**

Make & Model: BMW M340I, 3.0 XDRIVE ADPT LED HL (A) Engine No: 11646082B58B30B

Reg. Date: 24/08/2020 (Man. Year: 2020) Chassis No: WBA5U92060FJ96936

Colour: Blue Odometer: 28716 km

Engine Capacity: 2998 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 255/35 R19 Rear Tyre Size: 255/35 R19

Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,748.80	4,456.75	292.05	6.15
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,461.00	10,775.00	1,686.00	13.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	17,209.80	15,231.75	1,978.05	11.49
+ GST 7.00/7.00% (S\$)	1,204.69	1,066.22	138.47	11.49
Nett Amount (S\$)	18,414.49	16,297.97	2,116.52	11.49

INSPECTION

Date of Assignment: 06/06/2022

Date Inspected: 17/06/2022 Inspected At: Performance Motors Limited (Alexandra)
303 Alexandra Road, Sime Darby Performance Centre
Singapore 159941

Estimated Period of Repair: 10.0 days

Adjuster: MOHD RASUL**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 28 Jul 2022)

Parts: 143 BMW M340I 3.0 XDRIVE ADPT LED HL (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMU6329Z)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	10		*PLASTIC NUT FOR COARSE THREADED PIN	Not Necessary	8.50 FS	*- FS
2	1		*ALLOY RIM 8.5X19 DOUBLE SPK 792M	Scratched	1,827.95 FS	*1,827.95 FS
3	1		*REAR LH SIDE PANEL	Bent	1,760.05 FS	*1,760.05 FS
4	1		*LH C PILLAR REINFORCEMENT PLATE	Necessary	71.20 FS	*71.20 FS
5	1		*LH REINFORCEMENT PLATE SILL	Necessary	65.10 FS	*65.10 FS
6	10		*PLASTIC NUT	Necessary	8.50 FS	*8.50 FS
7	1		*SEALING WIND	Not Necessary	231.60 FS	*- FS
8	1		*CAVITY PROTECTION WAX REMOVER 500ML	Not Necessary	18.45 FS	*- FS
9	1		*BLIND RIVET AVIBVLB	Necessary	13.20 FS	*11.00 FS
			(24PCS)			
10	3		*SCREW (SF PLUS M5X15)	Necessary	1.80 FS	*1.80 FS
11	1		*(S/L) CLEANER R2 500ML	Not Necessary	14.80 FS	*- FS
12	1		*PUNCH RIVET N5	Not Necessary	16.50 FS	*- FS
			(30PCS)			
13	1		*(DG) BODYWORK ADHESIVE K5A (50ML)	Necessary	121.90 FS	*121.90 FS
14	1		*(DG) CLEANER R1 (100ML)	Necessary	26.15 FS	*26.15 FS
15	1		*PUNCH RIVET N4	Necessary	27.50 FS	*27.50 FS
			(27PCS)			
16	1		*(DG/SL) BODY ADHESIVE K5 (195ML)	Necessary	353.50 FS	*353.50 FS
17	1		*(SL/DG) SEALANT D2 290ML	Necessary	32.10 FS	*32.10 FS
18	1		*SUNDRIES	Necessary	150.00 FS	*150.00 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **4,748.80** **4,456.75**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE REAR LEFT FENDER AND MAKE GOOD OF REAR BUMPER	New	5,100.00	4,250.00
2	TO PAINTING REAR LEFT FENDER,REAR BUMPER,ROOF FRAME AND TRUNK PLATES	New	3,267.00	3,103.00
3	TO REMOVE AND INSTALL REAR HAT-TRAY, REAR SEAT, CARPET AND ROOF TOP LINING TO FACILITATE REPAIR	New	873.00	831.00
4	TO CHECK ELECTRICAL WIRING SYSTEM AND LIGHTING AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	168.00
5	TO REPLACE REAR WINDSCREEN GLASS	New	574.00	574.00
6	TO CONDUCT WATER LEAK TESTS	New	75.00	75.00
7	TO SUPPLY AND INSTALL FRONT OR REAR WINDSCREEN SOLAR FILM	New	531.00	0.00
8	TO REMOVE AND INSTALL FUSE BOX AT THE REAR SECTION TO FACILITATE REPAIR	New	531.00	504.00
9	TO REMOVE OLD PDC ASSEMBLY, REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECK FOR PROPER FUNCTION	New	177.00	168.00
10	TO REPLACE TYRE AND WHEEL RIM INCLUDING BALANCING. (1X)	New	94.00	94.00
11	TO CHECK STEERING GEOMETRY AND CONDUCT WHEEL ALIGNMENT IN ACCORDANCE WITH BMW SPECIFICATIONS. (1X)	New	531.00	504.00
12	TO CARRY OUT BODY CAVITY PRESERVATION. (FOR CUT PANEL)	New	531.00	504.00
Gross Labour Cost (S\$)			12,461.00	10,775.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >