



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLB 5499J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRT BONNET (WCP)	DISTORTED	480.00	480.00
2	FRT BONNET HINGE (WCP)	BENT	90.00	90.00
1	FRT BONNET LOCK (WCP)	DAMAGED	95.00	95.00
1	FRT BONNET INSULATOR (WCP)	CRUMPLED	115.00	115.00
10	INSULATOR CLIP (WCP)	NECESSARY	20.00	20.00
2	FRT BONNET SIDE SEAL (WITH CLIP) (WCP)	NOT NECESSARY	70.00	-
1	FRT BONNET LOCK CABLE (WCP)	JAMMED	45.00	45.00
1	FRT GRILLE (WCP)	SMASHED	270.00	270.00
1	GRILLE OUTER GARNISH (WCP)	SMASHED	180.00	180.00
2	GRILLE OUTER CHROME (WCP)	SMASHED	60.00	60.00
1	GRILLE LOGO (WCP)	NECESSARY	28.00	28.00
6	GRILLE CLIP (WCP)	NECESSARY	12.00	12.00
1	GRILLE CTR BRACKET (WCP)	CRACKED	35.00	35.00
2	GRILLE SIDE BRACKET (WCP)	CRACKED	50.00	50.00
1	FRT BUMPER (WCP)	DISTORTED	250.00	250.00
2	FRT BUMPER RETAINER (WCP)	NECESSARY	50.00	50.00
10	FRT BUMPER CLIP (WCP)	NECESSARY	20.00	20.00
1	FRT BUMPER REINFORCEMENT (WCP)	DENTED	280.00	280.00
1	FRT BUMPER LOWER GRILLE (WCP)	NOT NECESSARY	70.00	-
1	FRT BUMPER LOWER SPOILER (WCP)	NOT NECESSARY	135.00	-
2	HEADLAMP (WCP)	CRACKED	1,960.00	1,960.00
2	HEADLAMP LOWER BRACKET (WCP)	CRACKED	70.00	70.00
1	HEADLAMP SUPPORT PANEL (WCP)	DISTORTED	390.00	390.00
1	SUPPORT TOP GARNISH (WCP)	DEFORMED	50.00	50.00
8	TOP GARNISH CLIP (WCP)	NECESSARY	16.00	16.00
1	AIRCON CONDENSER (WCP)	DENTED	380.00	380.00
1	RADIATOR (WCP)	DENTED	850.00	850.00
1	AIRCON FAN COWLING (INDENT) (WCP)	CRACKED	145.00	145.00
1	AIRCON FAN MOTOR (WCP)	NOT NECESSARY	220.00	-
1	AIRCON FAN BLADE (WCP)	NOT NECESSARY	45.00	-
1	RADIATOR FAN COWLING (WCP)	CRACKED	105.00	105.00

Report Ref No. CS/LPC22005350/Avy3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	RADIATOR FAN MOTOR (WCP)	NOT NECESSARY	220.00	-
1	RADIATOR FAN BLADE (WCP)	NOT NECESSARY	55.00	-
1	RADIATOR TOP HOSE (WCP)	TWISTED	25.00	25.00
2	AIRCON SIDE DEFLECTOR (WCP)	DEFORMED	70.00	70.00
1	AIR DUCT (WCP)	DEFORMED	65.00	65.00
1	AIR HOSE (WCP)	DEFORMED	50.00	50.00
1	AIR CLEANER BOX TOP (WCP)	NOT NECESSARY	75.00	-
1	AIR CLEANER BOX LWR (WCP)	CRACKED	130.00	130.00
1	BATTERY BRACKET (WCP)	NOT NECESSARY	25.00	-
1	BATTERY TRAY (WCP)	DEFORMED	30.00	30.00
1	BATTERY 'POSITIVE' COVER (WCP)	DEFORMED	30.00	30.00
1	MANIFOLD (WCP)	CRACKED	320.00	320.00
1	MANIFOLD HOSE (WCP)	TORN	25.00	25.00
1	AIRCON COOLING PIPE (WCP)	NOT NECESSARY	135.00	-
1	AIRCON DISCHARGE PIPE (WCP)	NOT NECESSARY	150.00	-
1	RADIATOR SPARE TANK (WCP)	NOT NECESSARY	40.00	-
1	WASHER TANK (WCP)	DEFORMED	75.00	75.00
1	WASHER TANK NECK (WCP)	DEFORMED	35.00	35.00
2	FRT WIPER CORNER GARNISH (WCP)	NOT NECESSARY	60.00	-
2	FRT FENDER (WCP)	BUCKLED	380.00	380.00
2	FRT FENDER PROTECTOR (WCP)	DEFORMED	110.00	110.00
1	WIPER GARNISH (WCP)	NOT NECESSARY	190.00	-
1	THROTTLE BODY (WCP)	NOT NECESSARY	850.00	-
1	MANIFOLD HOSE CLIP (WCP)	NECESSARY	5.00	5.00
2	ARM CONDENSER BRACKET @\$16.00 (WCP)	BENT	32.00	32.00
2	HEADLAMP TOP BRACKET @\$18.00 (WCP)	CRACKED	36.00	36.00
1	FRT BONNET STAND (WCP)	MISSING	45.00	45.00
1	AMBIENCE SENSOR BRACKET (WCP)	MISSING	15.00	15.00
1	MANIFOLD "EARTH DREAM" EMBLEM (WCP)	NECESSARY	45.00	45.00
	COST PLUS 15%		1,486.35	1,135.35
			11,395.35	8,704.35
	<u>SPECIAL NETT ITEMS</u>			
1	FRT NUMBER PLATE (SN)	BENT	40.00	40.00

Report Ref No. CS/LPC22005350/Avy3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	RADIATOR COOLANT (SN)	NECESSARY	25.00	25.00
1	FRT BONNET SEALANT (SN)	NECESSARY	60.00	60.00
			125.00	125.00
	<u>LABOUR</u>			
	WIRE CHECKING.		40.00	30.00
	REMOVE & REFIX AIRCON AND GAS.		100.00	100.00
	RMEOVE & REFIX MANIFOLD & THROTTLE BODY.		250.00	250.00
	RESET SETTINGS.		200.00	100.00
	LABOUR CHARGE.		1,000.00	800.00
	SPRAY PAINTING.		1,200.00	1,000.00
			2,790.00	2,280.00
GRAND TOTAL			14,310.35	11,109.35
RECOMMENDED COST OF REPAIRS				11,109.35
LESS EXCESS				-500.00
NETT LIABILITY				10,609.35

Report Ref No. CS/LPC22005350/Avy3e2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.