



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLN 754S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BUMPER COVER FRT V40 (SN)	DEFORMED	1,865.70	1,679.13
1	BUMPER BRACKET FRT L (SN)	NOT NECESSARY	107.90	-
1	BUMPER BRACKET LHF V (SN)	NOT NECESSARY	182.10	-
1	BUMPER REINFORCEMENT (SN)	NOT NECESSARY	182.10	-
1	FENDER PANEL FRT LH (SN)	DENTED	1,262.80	1,136.52
1	WHEELARCH FRT LH V40 (SN)	NOT NECESSARY	253.00	-
1	ALLOY RIM 16 "MARKEB (SN)	CUT	749.10	674.19
10	BUMPER CLIP GREEN S6 (SN)	NOT NECESSARY	60.00	-
10	BUMPER CLIP XC90 16- (SN)	NOT NECESSARY	88.00	-
10	BUMPER CLIP 8x8.5 (SN)	NOT NECESSARY	82.00	-
10	BLIND RIVET 4.0*21 P (SN)	NOT NECESSARY	50.00	-
1	BUMPER INSTALLING MT (SN)	NOT NECESSARY	101.40	-
			4,984.10	3,489.84
	<u>LABOUR</u>			
	TO REPLACE LHF FENDER, FRONT BUMPER, BRACKETS, CLIPS, ETC.		2,550.00	1,275.00
	TO BLEND AND SPRAY PAINT ON LHF FENDER, FRONT BUMPER, ETC.		2,250.00	1,500.00
	TO REPLACE LHF RIM.		50.00	50.00
	WHEEL ALIGNMENT.		280.00	280.00
	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES.		588.00	588.00
			5,718.00	3,693.00
	GRAND TOTAL		10,702.10	7,182.84
	RECOMMENDED COST OF REPAIRS			7,182.84

Report Ref No. CS/FCI22005354/Ecy3e2

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.