

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	AXA INSURANCE			ef:	CS3/ASM22005360/Eqcm4	
	8 SHENTON WAY SINGAPORE 0688		ate:	10/06/2022		
	ATTN: KITTY TEO		Co	ode:	ASM	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SMK 4709B	Veh. Inspected		FBN 9486A	
	Policy No.	GA568506	Coverage (\$)		0.00	
	Claim No.	S2M0439A	Excess (\$)		0.00	
	Assign From	KITTY TEO	Assign Date		06/06/2022	
2.	2. Vehicle Particulars & Condition					
	Make & Model	HONDA CB150R	c.c		149	
	Engine No.	HIDDEN	Year of Reg.		2019	
	Chassis No.	MLHKC2886J5029977	Colour		BLACK	
	Odometer	30660 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3.	Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	120/60 R17	DIABLO		4 mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre	150/60 R17	DIABLO		4 mm	
	L/H Rear Tyre				mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION AND N/S BODY.					
5.	General Information					
	Accident Date	03/06/2022	Inspect Date / Tin	ne	08/06/2022 ( 02:56 PM )	
	Survey held at AHFOOKMOTOR.COM LLP					
	5 SOON LEE STREET #01-15 PIONEER POINT SINGAPORE 627607					
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000-\$3,000					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days					
			A CN 40000E0C0/E ~ ~			

Report Ref No. CS3/ASM22005360/Eqcm4

Inspected By

CHEN TSUE YEE

K.K.LAU CPT(RET)

**Automotive Assessor** 

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$ 

REGD Auto Consultant-SAE, Licensed Appraiser