

7PAYA.
Celia.

Smu8798P 2020 August.
Mazda 2 HB 1496cc
Jm6DJ2HAA01300603.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Front Bumper	Distorted	874	✓
Front Bumper Clips	new	30(SN)	✓
Front Bumper Side Holder LH.	Repd	36	✓
Front Bumper Fog Lamp LH.	} at car	369	✗
Front Bumper Fog Lamp Cover LH		58	✗
Front Bumper Fog Lamp Chrome Moulding LH.	new	65	✗
Headlamp LH.	Cracked	2894	✓
Front LH Fender	Dented	339	✓
Front LH Fender Inner Shield Tom		110	✓
Front LH Fender Inner Shield Clips	new	30(SN)	✓
Front LH Fender Bracket.	Bent	52	✓
Bonnet	Repair	738	✗
Front LH Wheel Rim.	at	1200 500(SN)	

SMU8798P.

Front LH Tyre.	New	280 (SN) +
Front LH Lower Arm.	Best	388 -
Front LH Shock Absorber	HP on	361 +
Front LH Knuckle Arm.	Dund	356. ✓
Front LH Wheel Hub c/w Bearing.	Dund	295. -
DC Converter Control Unit.	Quib	464 -
	5818.	S.N. 560
	4654.40	

Panel Beating
Spray Painting.

Wiring.

To spray buff coat

To dismantle front undercarriage.

To perform wheel alignment

To perform diagnostic test.

~~800~~ 600

~~900~~ 600

~~50~~ 30

~~150~~ 50

~~380~~ 200

~~150~~ 80

~~200~~ 100

total: 6874.40

A/S: 5.5K.

06 Days.

5,500
06 days