

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22005366/EVY3M4**Date:** 04/08/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00139652103

Claimant Vehicle No : SLT969H **Insured Vehicle No :** GBB2872C

Date of Loss: 31/05/2022 Nature of Claim: TP Claim No: SNM22D203837/C02/LEEPG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLT969H**

Make & Model: SUBARU LEVORG, 1.6 GT-S AWD CVT (A) Engine No: FB16CA71640

Reg. Date: 22/09/2017 (Man. Year: 2017) Chassis No: JF1VM4K55JG006067

Colour: Grey Odometer: 80014 km

Engine Capacity: 1600 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R18 Rear Tyre Size: 225/45 R18

Front Left Side: Yokohama 4 mm Rear Left Side: Yokohama 4 mm

Front Right Side: Yokohama 4 mm Rear Right Side: Yokohama 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,524.24	1,958.80	565.44	22.40
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,945.00	3,975.00	970.00	19.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,469.24	5,933.80	1,535.44	20.56
+ GST 7.00/7.00% (S\$)	522.85	415.37	107.48	20.56
Nett Amount (S\$)	7,992.09	6,349.17	1,642.92	20.56

INSPECTION

Date of Assignment: 06/06/2022

Date Inspected: 08/06/2022 Inspected At: Motor Image Enterprises Pte Ltd (Leng Kee)
25 Leng Kee Road
Singapore 159097

Estimated Period of Repair: 6.0 days

Adjuster: CHEN TSUE YEE**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

NOTE: TP CONVERT TO OD CLAIM
(REPAIR COST NOT CONCLUDE)
(EXCLUDE CHECK ITEMS S\$500.00 NETT)

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 04 Aug 2022)

Parts: M1-SUV SUBARU LEVORG 1.6 GT-S AWD CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLT969H)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*VALVE TPMS ASSY	Necessary	185.00 FN	*185.00 FN
2	1		*PNL SD OUT QTR RPLH	Dented	888.00 FN	*888.00 FN
3	1		*QTR PNL R END CPL LH	Necessary	22.20 FN	*22.20 FN
4	1		*PNL COMPL DR R WLH	Dented	666.00 FN	*666.00 FN
5	1		*LATCH&ACT AY DR RLH	Not Necessary	185.00 FN	*- FN
6	1		*HANDLE OUT DR	Not Necessary	48.10 FN	*- FN
7	1		*WSTR OUT DR R LH	Not Necessary	96.20 FN	*- FN
8	1		*WSTR DR R LH	Not Necessary	129.50 FN	*- FN
9	1		*GLASSRUN DR R WLH	Not Necessary	62.90 FN	*- FN
10	1		*WSTR BODY SD FLG R	Not Necessary	85.10 FN	*- FN
11	1		*WDW GL ASSY R QTRLH	Necessary	599.40 FN	*599.40 FN
12	1		*DAM RUBBER A	Necessary	7.40 FN	*7.40 FN
13	1		*DAM RUBBER B	Necessary	7.40 FN	*7.40 FN
14	1		*TAPE DR SASH R F LH	Necessary	18.50 FN	*18.50 FN
15	1		*TAPE DR SASH R M LH	Necessary	14.80 FN	*14.80 FN
16	1		*TAPE DR SASH R R LH	Necessary	14.80 FN	*14.80 FN
17	1		*SUNDRIES	Necessary	100.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$\$)	3,130.30	2,443.50
- Nett Item Discount on N Items 20.00/20.00% (\$\$)	606.06	484.70
Total Parts (\$\$)	2,524.24	1,958.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPAIR/REPLACE LH REAR DOOR, LH REAR FENDER, LH REAR ROCKER PANEL & PANEL	New	2,240.00	2,240.00
2	RESPRAY REAR LH DOOR, REAR LH FENDER, REAR LH ROCKER PANEL & PANEL	New	1,680.00	1,260.00
3	TRANSFER DOOR REAR LH MECHANISM	New	200.00	150.00
4	REMOVE & INSTALL LH REAR QUARTER GLASS	New	180.00	180.00
5	CONDUCT REAR PROTECTANT COATING (* Check)	New	500.00	0.00
6	SUPPLY & INSTALL LH REAR QUARTER GLASS TINTED FILM	New	145.00	145.00
Gross Labour Cost (S\$)			4,945.00	3,975.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >