

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: GBB 2872C

Policy No. DMCVSNW00139652103

Claims No. SNM22D203837/C02/LEEPG


Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SLT969H

Yr Regn: 22/9/17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Subaru Levorg c.c. 1600

Colour: Gray

A/C: Insured / Std / NI / NA

Sp. Reading: 80044

T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JFTRM4K 5536006067

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: NII / S/Rim / STD A/Rim or

Tyre Size: F: 215/45R18

R: "

BS / DYN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO YOKO

Front

R/Bal. 4 mm

L/Bal. 4 mm

D.O.A. 3/5/22

Survey held at Motor Image

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date/Time Action/Instruction

MV-85K

3/8/22 Submit preli report-revised fig \$5933.80 check items \$500

Note: TP convert to OD claim

Date/Time, File Pass to?



: Preli. Report

1)



: Final Report

Date/Time, File Return to?

2) 3/8/22-typist

Report Format: Merimen

Lump Sum / L.B.F. (\$ \_\_\_\_\_)

Days Of Repair: 6

Resurvey No. of Trip: \_\_\_\_\_

Add Fee:



: Site Insp (\$ \_\_\_\_\_)



: Interview (\$ \_\_\_\_\_)



: Tech, Invs (\$ \_\_\_\_\_)



: Weekend (\$ \_\_\_\_\_)

Survey Fee:

Transportation:

\$ + RS. \$ \_\_\_\_\_

Photos

Others

TOTAL

MOTORIMAGE ENTERPRISES PTE. LTD.  
25 LENG KEE ROAD  
SINGAPORE 159097

ESTIMATE : ACCIDENT/BODY REPAIRS  
WORKSHOP : LENG KEE  
CONTACT NO :  
REFERENCE : INS/IC/CHI/0095/2022  
DATE : 03-JUN-2022

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD  
3 ANSON ROAD  
#15-00 SPRINGLEAF TOWER  
SINGAPORE S(079909)  
TEL : 6389 6111  
FAX : 6222 1033

OWNER'S NAME : LIM TONG HUAY ( LIN DONGHUAI )  
ADDRESS : APT BLK 119 TECK WHYE LANE  
#09-794  
S(680119)  
TELEPHONE NO : 9796 4421

TYPE OF CLAIM : THIRD PARTY CLAIM  
POLICY NO : 1700055832-04  
VEHICLE NO : SLT969H  
MODEL CODE : VM4DK15  
MODEL/YEAR : LEVORG 1.6GT-S AWD CVT  
ENGINE NO : FB16CA71640  
CHASSIS NO : JF1VM4K55JG006067  
MILEAGE : 1 KM  
DATE IN : 03/06/2022  
LIABILITY : 0.00  
EXCESS CLAUSE : 0.00  
ESTIMATE BY : SAYEDINAH ALI\*\*  
ACCIDENT DATE : 31/05/2022

Print Date : 03/06/2022  
Print Time : 14:34:52

IMAGE ENTERPRISES PTE. LTD.  
LENG KEE ROAD  
SINGAPORE 159097

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLT969H

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 TPCLAIM	CONDUCT BODYWORK REPAIR (THIRD PARTY CLAIM) AGAINST GBB2872C - CN TAIPING INSURED		
2 ZZ/001	CONDUCT TP CLAIM CN TAIPING DATE:31/05/2022 TIME: 0907HRS LOCATION:JLN JURONG KECHIL TO UPP BKT TIMH		
3 ZZ/002	REPAIR/REPLACE LH REAR DOOR, LH REAR FENDER, LH REAR ROCKER PANEL & PANEL <i>560</i>	2240.00	✓
4 ZZ/003	RESPRAY REAR LH DOOR, REAR LH FENDER, REAR LH ROCKER PANEL & PANEL <i>470</i>	1680.00	<i>1260</i>
5 ZZ/004	TRANSFER DOOR REAR LH MECHANISM	200.00	<i>150</i>
6 ZZ/005	REMOVE & INSTALL LH REAR QUARTER GLASS	180.00	✓
7 ZZ/006	CONDUCT REAR PROTECTANT COATING <i>(sahm agreed)</i>	500.00	?
8 ZZ/007	SUPPLY & INSTALL LH REAR QUARTER GLASS TINTED FILM	145.00	✓
9 ZZ/008	SUNDRIES <i>(sahm agreed)</i>	100.00	<i>77</i>
TOTAL LABOUR CHARGES		5045.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLT969H

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			S/LIST REMARKS
			NETT	LIST	S/NETT	
1	VALVE TPMS ASSY	28103FJ003	185.00	/	NEC	
2	PNL SD OUT QTR RPLH	51439VA0319P	888.00	/	DD	
3	QTR PNL R END CPLLH	51445VA0309P	22.20	/	NEC	
4	PNL COMPL DR R WLH	60409VA0509P	666.00	/	DD	
5	LATCH&ACT AY DR RLH	61035VA210	185.00	X	nn	
6	HANDLE OUT DR	61160FJ000EN	48.10	X	nn	
7	WSTR OUT DR R LH	62280VA131	96.20	X	nn	
8	WSTR DR R LH	63512VA110	129.50	X	nn	
9	GLASSRUN DR R WLH	63527VA130	62.90	X	nn	
10	WSTR BODY SD FLG R	63572VA021	85.10	X	nn	
11	WDW GL ASSY R QTRLH	65210VA171	599.40	X	NEC	
12	DAM RUBBER A	65245VA000	7.40	/	NEC	
13	DAM RUBBER B	65245VA010	7.40	/	NEC	
14	TAPE DR SASH R F LH	90422VA570	18.50	/	NEC	
15	TAPE DR SASH R M LH	90422VA590	14.80	/	NEC	
16	TAPE DR SASH R R LH	90422VA610	14.80	/	NEC	
SUB TOTAL			3030.30	0.00	0.00	0.00
LESS DISCOUNT ( NETT-20 %)			606.06	0.00	0.00	0.00
GRAND TOTAL			2424.24	0.00	0.00	0.00
OVERALL TOTAL			2424.24			

LEGEND: REMARKS( OK ) = APPROVED, REMARKS( X ) = NOT APPROVED



SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLT969H

TOTAL LABOUR CHARGES	5045.00
TOTAL SPARE PARTS CHARGES	2424.24
GRAND TOTAL	7469.24 *

\* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME :  
SURVEYED DATE :  
AUTHORIZED DATE :  
EXCESS CLAUSE : 0.00  
LIABILITY : 0.00  
REMARKS :

Stere (LKK)  
8/6/22, 10.00am

WZ MZ  
P/P  
My BL Sy  
6 yrs

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: