11/8/22, 1:52 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22005368/EVY3Q2

08/11/2022 Date:

REFERENCE

China Taiping Insurance Handling Insurer:

(Singapore) Pte. Ltd.

Policy No: DMCVSNA00094932106

GBE114E

Claimant Vehicle

SLH5890E

Insured

No:

Vehicle No:

Claim

Date of Loss:

30/05/2022

Nature of TP Claim:

SNM22D203850/C02/CHNGPW

Yes

DESCRIPTION & IDENTIFICATION OF VEHICLE

SLH5890E Reg No:

SUBARU FORESTER, 2.0 XT AWD CVT (A) Make & Model:

Engine No: FA20B840893

Reg. Date: 11/11/2016 (Man. Year: 2016) Chassis No: JF1SJGK85GG078874 Odometer: 86944 km

Colour: Black

Engine Capacity:

1998 cc

N/A

Market Value/New Car Price: Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable):

Handbrake (Serviceable): **Engine Modification:** Pre-accident Condition: Yes Nο

CONDITION OF TYRES

Front Tyre Size: 255/55 R18 Rear Tyre Size: 255/55 R18 Front Left Side: Rear Left Side: Michelin 5 mm Michelin 5 mm Front Right Side: Rear Right Side: Michelin 5 mm Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	931.84	598.40	333.44	35.78
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,130.00	980.00	150.00	13.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,061.84	1,578.40	483.44	23.45
+ GST 7.00/7.00% (S\$)	144.33	110.49	33.84	23.45
Nett Amount (S\$)	2,206.17	1,688.89	517.28	23.45

INSPECTION

Date of Assignment: 06/06/2022

Motor Image Enterprises Pte Ltd (Leng Kee)

Date Inspected: 29/06/2022 Inspected At: 25 Leng Kee Road

Singapore 159097

Estimated Period of Repair: 3.0 days

Adjuster: **CHEN TSUE YEE** Manager: **VERON CHEN**

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

11/8/22, 1:52 PM

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 08 Nov 2022)

Parts: M1-SUV SUBARU FORESTER 2.0 XT AWD CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLH5890E)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER FACE F (FOR UL/W)	Cut	610.50 FN	*610.50 FN
2	1		*GRILLE ASSY F LWRHG	Not Necessary	316.80 FN	*- FN
3	1		*SUNDRIES	Necessary	100.00 FS	*20.00 FS
4	1		*FRONT NUMBER PLATE	Broken	90.00 FS	*90.00 FS
F=Fra	nchise	part. S=SpcNet	t. N=NettItemDisc.			
				Sub Total (S\$)	1,117.30	720.50
			- Nett Item Discount o	on N Items 20.00/20.00% (S\$)	185.46	122.10
				Total Parts (S\$)	931.84	598.40
			Report was unsubmitt	ed during this print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount			
Lab	our Items						
1	REPAIR FRONT BUMPER & GRILLE	New	560.00	560.00			
2	RESPRAY FRONT BUMPER	New	420.00	420.00			
3	REMOVE/REFIX FRT HEADLAM WASHER & PIPING	New	150.00	0.00			
		Gross Labour Cost (S\$)	1,130.00	980.00			
	Report was unsubmitted during this print-out.						

< END OF ESTIMATES >