7/19/22, 9:03 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

CS/CTI22005372/KVY3M4 Our File No:

19/07/2022 Date:

REFERENCE

China Taiping Insurance Handling Insurer:

(Singapore) Pte. Ltd.

Policy No: DMCVSNW00062092100

Claimant Vehicle

GBK4109M

Insured Vehicle No:

GBH753U

TP

No:

Date of Loss:

28/05/2022

Nature of

Claim

Claim:

Engine No:

Chassis No:

Odometer:

SNM22D203831/C02/TANCHC

JN1YAAM20Z0001082

Yes

HR16166427D

52511 km

DESCRIPTION & IDENTIFICATION OF VEHICLE

GBK4109M Reg No:

Make & Model: NISSAN NV200, 1.6 PETROL (A)

Reg. Date: 20/07/2020 (Man. Year: 2020)

Silver

Colour: **Engine Capacity:** 1598 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Footbrake (Serviceable): Yes

Handbrake (Serviceable): **Engine Modification:** Pre-accident Condition: Yes Nο

CONDITION OF TYRES

Front Tyre Size: 175/70 R14 Rear Tyre Size: 175/70 R14 Front Left Side: Rear Left Side: West Lake 9 mm West Lake 9 mm Front Right Side: Rear Right Side: West Lake 9 mm West Lake 9 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|------------------------|------------|------------|------------|--------|
| Parts | 3,006.80 | 2,618.22 | 388.58 | 12.92 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 1,870.00 | 1,440.00 | 430.00 | 22.99 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Gross Total (S\$) | 4,876.80 | 4,058.22 | 818.58 | 16.79 |
| + GST 7.00/7.00% (S\$) | 341.38 | 284.08 | 57.30 | 16.78 |
| Nett Amount (S\$) | 5,218.18 | 4,342.30 | 875.88 | 16.79 |

INSPECTION

Date of Assignment: 07/06/2022

Falcon-Air Auto Services Pte Ltd (Sin Ming) Date Inspected: 07/06/2022 Inspected At:

176 Sin Ming Drive #01-06, Sin Ming Autocare

Singapore 575721

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG Manager: **VERON CHEN**

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 19 Jul 2022)

Parts: N/A NISSAN NV200 1.6 PETROL (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for GBK4109M)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-------|---------|--------------|----------------------------------|-------------------------------|-------------|--------------|
| 1 | 1 | | *TAILGATE | Bent | 1,635.00 FN | *1,635.00 FN |
| 2 | 1 | | *TAILGATE LOGO | Necessary | 64.90 FN | *64.90 FN |
| 3 | 1 | | *TAILGATE EMBLEM - NV200 | Necessary | 94.40 FN | *94.40 FN |
| 4 | 1 | | *REAR END PANEL (OUTER) | Repair | 193.50 FN | *- FN |
| 5 | 1 | | *REAR END PANEL TOP GARNISH | Serviceable | 87.90 FN | *- FN |
| 6 | 1 | | *TAILGATE WEATHERSTRIP | Dented / Dislodged | 106.40 FN | *106.40 FN |
| 7 | 1 | | *REAR BUMPER | Buckled | 485.90 FN | *481.10 FN |
| 8 | 1 | | *REAR BUMPER SPONGE | Cracked | 94.00 FN | *94.00 FN |
| 9 | 1 | | *6 PAX STICKER | Necessary | 25.00 FS | *12.00 FS |
| 10 | 1 | | *70 KM/H STICKER | Necessary | 25.00 FS | *12.00 FS |
| 11 | 6 | | *REAR END PANEL TOP GARNISH CLIP | Necessary | 60.00 FS | *60.00 FS |
| 12 | 1 | | *TAILGATE GLASS SEALANT | Necessary | 45.00 FS | *40.00 FS |
| 13 | 12 | | *REAR BUMPER CLIP | Necessary | 36.00 FS | *36.00 FS |
| 14 | 1 | | *SET REVERSE SENSOR | Shorted | 250.00 FS | *200.00 FS |
| 15 | 1 | | *TAILGATE BODY SEALANT | Necessary | 80.00 FS | *30.00 FS |
| F=Fra | ınchise | part. S=SpcN | lett. N=NettItemDisc. | - | | |
| | | | | Sub Total (S\$) | 3,283.00 | 2,865.80 |
| | | | - Nett Item Discount o | on N Items 10.00/10.00% (S\$) | 276.20 | 247.58 |
| | | | | Total Parts (S\$) | 3,006.80 | 2,618.22 |
| | | | Report was unsubmitted o | during this print-out. | | |

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|------------|---|-----------|------------|----------|
| <u>Lab</u> | our Items | | | |
| 1 | TO REMOVE/REFIX TAILGATE GLASS | New | 120.00 | 120.00 |
| 2 | TO REMOVE/REFIX TAILGATE MECHANISM | New | 100.00 | 60.00 |
| 3 | TO REFIT REVERSE SENSOR IN NEW BUMPER | New | 50.00 | 50.00 |
| 4 | TO RUSTPROOF ACCIDENT DAMAGE AREA | New | 150.00 | 60.00 |
| 5 | TO CUT OUT/RE-WELD REAR END PANEL OUTER, REPAIR REAR END PANEL INNER, REAR CHASSIS INCLUDING REPLACEMENT OF PARTS | New | 700.00 | 650.00 |
| 6 | TO SPRAY PAINT ON TAILGATE, REAR END PANEL OUTER/INNER | New | 750.00 | 500.00 |
| | Gross Labour Cost (S\$) | | 1,870.00 | 1,440.00 |
| | Report was unsubmitted during this | print-out | | |

< END OF ESTIMATES >