

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FB3 3108Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	R/MIRROR	BROKEN	75.00	40.00
1	CLUTCH LEVER	CUT	89.00	30.00
1	BRAKE LEVER	CUT	89.00	30.00
1	SIDE STAND	NOT NECESSARY	148.00	-
1	L/R FRONT FOOT REST	BENT	134.00	120.00
1	R/ REAR FOOT REST	NOT NECESSARY	134.00	-
1	EXHAUST COVER LONG / SHORT	CUT	348.00	150.00
1	HEADLIGHT COWLING (HEADLAMP)	CUT	146.00	146.00
1	BIKE PLATE (HANDLE GRIP)	TORN	15.00	15.00
1	L/R HANDLE BAR	BENT	155.00	155.00
1	L/R TAIL COVER (FRONT BODY COVER)	CUT	189.00	189.00
1	FRONT FENDER	CUT	126.00	105.00
1	BASKET (REAR CARRIER BRACKET)	BENT	78.00	78.00
	LESS 10% DISCOUNT		-172.60	-105.80
			1,553.40	952.20
	<u>LABOUR</u>			
	BODY FRAME RE-ALIGNMENT.		800.00	150.00
	FORK RE-ALIGNMENT.		380.00	200.00
	FRONT RIM RE-ALIGNMENT.		380.00	150.00
	LABOUR TO DISMANTLE AND ASSEMBLE PARTS.		1,200.00	300.00
			2,760.00	800.00
	GRAND TOTAL		4,313.40	1,752.20
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,400.00

Report Ref No. CS3/ASM21005520/Evy3e2-1

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.