

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22005389/UVY3N2**Date:** 14/06/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMHCSNW00003742200

Claimant Vehicle No : SMJ7908D **Insured Vehicle No :** SMJ5623M

Date of Loss: 17/04/2022 Nature of Claim: TP Claim No: SNM22D203973/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMJ7908D**

Make & Model: VOLKSWAGEN GOLF, 2.0 GTI (A) Engine No: CCZ013701

Reg. Date: 26/10/2009 (Man. Year: 2009) Chassis No: WVVZZZ1KZ9W547063

Colour: Green Odometer: 161917 km

Engine Capacity: 1984 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/40R18 Rear Tyre Size: 235/40R18

Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6 mm

Front Right Side: Goodyear 6 mm Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre tread depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--|-------------------|-------------------|-------------------|---------------|
| Parts | 9,806.49 | 882.90 | 8,923.59 | 91.00 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 2,630.00 | 770.00 | 1,860.00 | 70.72 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 12,436.49 | 1,652.90 | 10,783.59 | 86.71 |
| Approved Total (Overridden) (S\$) | | 1,300.00 | | |
| Nett Amount (S\$) | 12,436.49 | 1,300.00 | 11,136.49 | 89.55 |

INSPECTION

Date of Assignment: 08/06/2022

Date Inspected: 07/06/2022 Inspected At: 15 KAKI BUKIT ROAD 4
#01-05/53 BARTLEY BIZ
REPAIRER: ASIA MOTORSPORTS SOLUTION
PTE LTD

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

| | | |
|----------------------|--|---|
| Part Source: | MRM-SG | Version: 1.0 (Last Synchronised: 14 Jun 2022) |
| Parts: | 144 | VOLKSWAGEN GOLF 2.0 GTI (A) (Catalogue:Merimen Singapore 1.0) |
| Labour: | Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for SMJ7908D) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|---|--------------------------------|-------------|------------|
| 1 | 1 | | *FRONT BUMPER ASSY | Repair | 1,671.20 FL | *- FL |
| 2 | 1 | | *FRONT BUMPER LEFT RETAINER | Not Necessary | 88.50 FL | *- FL |
| 3 | 1 | | *FRONT BUMPER LEFT BRACKET | Not Necessary | 84.30 FL | *- FL |
| 4 | 1 | | *FRONT BUMPER REINFORCEMENT | Not Necessary | 425.20 FL | *- FL |
| 5 | 1 | | *FRONT BUMPER SPONGE | Not Necessary | 170.20 FL | *- FL |
| 6 | 1 | | *FRONT BUMPER LOWER GRILLE | Not Necessary | 180.40 FL | *- FL |
| 7 | 1 | | *FRONT BUMPER TOW COVER | Not Necessary | 78.80 FL | *- FL |
| 8 | 1 | | *FRONT BUMPER LEFT FOG LAMP | Not Necessary | 282.10 FL | *- FL |
| 9 | 1 | | *FRONT BUMPER LEFT FOG LAMP COVER | Not Necessary | 170.60 FL | *- FL |
| 10 | 1 | | *FRONT LEFT SPRAY NOZZLE | Not Necessary | 178.40 FL | *- FL |
| 11 | 1 | | *FRONT LEFT SPRAY NOZZLE COVER | Not Necessary | 38.90 FL | *- FL |
| 12 | 1 | | *FRONT BONNET LOCK MECHANISM | Not Necessary | 151.70 FL | *- FL |
| 13 | 1 | | *FRONT LOCK BRACE PANEL | Not Necessary | 79.50 FL | *- FL |
| 14 | 1 | | *FRONT LEFT HEADLAMP ASSY | Cracked | 991.40 FL | *981.00 FL |
| 15 | 1 | | *FRONT SUPPORT PANEL ASSY | Not Necessary | 891.70 FL | *- FL |
| 16 | 2 | | *FRONT SUPPORT PANEL DEFLECTOR | Not Necessary | 113.20 FL | *- FL |
| 17 | 10 | | *FRONT BUMPER CLIPS | Not Necessary | 60.00 FS | *- FS |
| 18 | 6 | | *FRONT BUMPER LOWER GRILLE CLIPS | Not Necessary | 40.00 FS | *- FS |
| 19 | 1 | | *FRONT CARBON FIBER GRILLE ASSY | Not Necessary | 450.00 FS | *- FS |
| 20 | 1 | | *FRONT CARBON FIBER GRILLE EMBLEM | Not Necessary | 80.00 FS | *- FS |
| 21 | 4 | | *FRONT GRILLE CLIPS | Not Necessary | 40.00 FS | *- FS |
| 22 | 1 | | *FRONT CARBON FIBER BONNET ASSY | Not Necessary | 1,650.00 FS | *- FS |
| 23 | 1 | | *FRONT NO PLATE WITH GARNISH | Not Necessary | 100.00 FS | *- FS |
| 24 | 1 | | *SET FRONT PARKING SENSOR | Not Necessary | 1,000.00 FS | *- FS |
| 25 | 1 | | *FRONT BUMPER CARBON FIBER LOWER SPOILER ASSY (CRACKED) | Not Consistent With The Impact | 1,200.00 FS | *- FS |
| 26 | 8 | | *FRONT BUMPER CARBON FIBER LOWER SPOILER CLIPS | Not Necessary | 50.00 FS | *- FS |
| 27 | 1 | | *FRONT BUMPER CARBON FIBER LOWER SPOILER SEALANT | Not Necessary | 100.00 FS | *- FS |

F=Franchise part. S=SpcNett. L=ListItemDisc.

| | | |
|--|------------------|---------------|
| Sub Total (\$) | 10,366.10 | 981.00 |
| - List Item Discount on L Items 10.00/10.00% (\$) | 559.61 | 98.10 |
| Total Parts (\$) | 9,806.49 | 882.90 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------------------|--|----------|-----------------|---------------|
| Labour Items | | | | |
| 1 | TO PUTTY AND SPRAY PAINTING FRONT AND FRONT LEFT PORTION | New | 1,000.00 | 400.00 |
| 2 | LABOUR FOR PANEL BEATING,CUT,WELD,STRAIGHTEN FRONT AND FRONT LEFT AFFECTED AREA AND REPLACE FRONT AND FRONT LEFT DAMAGED PARTS } | New | 1,000.00 | 300.00 |
| 3 | TO REPAIR,STRAIGHTEN AND ALIGN FRONT LEFT FENDER ASSY } | New | 180.00 | 0.00 |
| 4 | TO CHECK WIRING AND FOCUS FRONT HEADLAMP | New | 50.00 | 20.00 |
| 5 | TO REMOVE AND INSTALL FRONT BONNET LOCK MECHANISM | New | 80.00 | 0.00 |
| 6 | TO APPLY ANTI RUST PROOFING TO FRONT AND FRONT LEFT AFFECTED AREA | New | 140.00 | 0.00 |
| 7 | TO SYNCHRONISE THE FRONT PARKING SENSOR AND CHECK FOR FUNCTION | New | 80.00 | 50.00 |
| 8 | TOWING SERVICE | New | 100.00 | 0.00 |
| Gross Labour Cost (\$\$) | | | 2,630.00 | 770.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >