

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/TMI22005390/TNY3Q2**Date:** 16/08/2022REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MR005857
Claimant Vehicle No :	SHA5383L	Insured Vehicle No :	SMA2628S
Date of Loss:	06/06/2022	Nature of Claim:	TP
		Claim No:	M2202908

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHA5383L	Engine No:	G4LEKU407489
Make & Model:	HYUNDAI AE IONIQ HEV FL, 1.6 DCT (A)	Chassis No:	KMHC851CVLU189571
Reg. Date:	11/03/2020 (Man. Year: 2019)	Odometer:	361699 km
Colour:	Blue		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,886.64	378.60	1,508.04	79.93
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	1,170.00	630.00	540.00	46.15
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,067.64	1,019.60	2,048.04	66.76
+ GST 7.00/7.00% (S\$)	214.73	71.37	143.36	66.76
Nett Amount (S\$)	3,282.37	1,090.97	2,191.40	66.76

INSPECTION

Date of Assignment:	07/06/2022	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	07/06/2022	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	2.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 15 Aug 2022)**Parts:** 143 HYUNDAI AE IONIQ HEV FL 1.6 DCT (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** (Unsubmitted, no print-code for SHA5383L)**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	459.40 FL	*- FL
2	1		*REAR BUMPER CENTRE MOULDING	Deformed	451.25 FL	*451.25 FL
3	1		*REAR BUMPER REINFORCEMENT BEAM	Not Necessary	394.80 FL	*- FL
4	2		*REAR BUMPER REINFORCEMENT BEAM TOP BRACKET L/R	Not Necessary	276.20 FL	*- FL
5	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
6	2		*REAR BUMPER SIDE RETAINER -L/R	Not Necessary	111.60 FL	*- FL
7	1		*REAR BUMPER FOG LAMP	Not Necessary	201.50 FL	*- FL
8	1		*REAR NUMBER PLATE LIGHT LAMP	Not Necessary	85.30 FL	*- FL
9	1		*REAR NUMBER PLATE W/HOLDER	Not Necessary	55.00 FS	*- FS
10	1		*REAR REVERSE SENSOR	Not Necessary	180.00 FS	*- FS
11	1		*REAR BUMPER MAT	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	2,287.05	473.25
- List Item Discount on L Items 20.00/20.00% (\$)	400.41	94.65
Total Parts (\$)	1,886.64	378.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	OD/TP Case (Insurer)	11.00	11.00
			Sub Total (\$\$)	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	750.00	350.00
2	SPRAY PAINTING	New	300.00	250.00
3	CHECK LIGHTING % WIRING	New	60.00	0.00
4	REMOVE/REFIX REVERSE SENSOR	New	60.00	30.00
			Gross Labour Cost (\$\$)	630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >