6/22/22, 9:42 AM Adjuster Report

### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI22005391/KQY3N2

22/06/2022 Date:

**REFERENCE** 

China Taiping Insurance Handling Insurer:

(Singapore) Pte. Ltd.

Policy No:

DMCVSNW00099412102

**Claimant Vehicle** 

SNB5505B

Insured

**GBE1214T** 

No:

Vehicle No:

Date of Loss:

26/05/2022

Nature of Claim: TP

Claim

SNM22D203972/C02/LEWLC

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

SNB5505B Reg No:

TESLA MODEL 3 PERFORMANCE, 2.0 E (A) Make & Model:

Engine No: **HIDDEN** 

Reg. Date: 06/09/2021 (Man. Year: 2021) Chassis No: Odometer:

LRW3F7EL8MC263541 15999 km

Yes

Colour: Black

**Engine Capacity:** Market Value/New Car Price:

Sum Insured (S\$):

0 сс

N/A Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable):

Handbrake (Serviceable): **Engine Modification:** Pre-accident Condition: Yes Nο

**CONDITION OF TYRES** 

Front Tyre Size: 235/35R20 Rear Tyre Size: 235/35R20 Front Left Side: Pirelli 9 mm Rear Left Side: Pirelli 9 mm Front Right Side: Pirelli 9 mm Rear Right Side: Pirelli 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	657.19	657.19	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	840.00	545.00	295.00	35.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,497.19	1,202.19	295.00	19.70
+ GST 7.00/7.00% (S\$)	104.80	84.15	20.65	19.70
Nett Amount (S\$)	1,601.99	1,286.34	315.65	19.70

**INSPECTION** 

Date of Assignment: 07/06/2022

Optima Werkz Pte Ltd (HQ)

10 Ang Mo Kio Industrial Park 2A, #01-05 AMK Date Inspected: 08/06/2022 Inspected At:

Autopoint

Singapore 568047

Estimated Period of Repair: 2.0 days

Adjuster: **KENNETH KONG** Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

6/22/22, 9:42 AM Adjuster Report

Different 1 cents -Finalise confirm amount: \$1,202.20

6/22/22, 9:42 AM Adjuster Report

### **REPAIR DETAILS**

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 22 Jun 2022)

Parts: 143 TESLA MODEL 3 PERFORMANCE 2.0 E (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's (Price-denominated Standard List) **Print Code:** (Unsubmitted, no print-code for SNB5505B)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

#### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Buckled	663.55 FL	*663.55 FL
2	1		*FRONT BUMPER CLIPS	Necessary	60.00 FS	*60.00 FS
F=Fra	nchise	part. S=SpcNett	L=ListItemDisc.	,		
				Sub Total (S\$)	723.55	723.55
			- List Item Discount of	n L Items 10.00/10.00% (S\$)	66.36	66.36
				Total Parts (S\$)	657.19	657.19
			Report was unsub	mitted during this print-out.		

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	LABOUR CHARGES TO REMOVE,REPLACE,REFIX,REPAIR & READJUST ACCIDENT AREAS	New	200.00	200.00
2	LABOUR CHARGES FOR PAINTING & FURNISHING MATERIALS AT ACCIDENT AREAS	New	300.00	220.00
3	LABOUR CHARGES TO REMOVE & REFIX FRONT PARKING SENSOR	New	100.00	50.00
4	TO DIAGNOSIS FAULT CODE & RESET MEMORY	New	120.00	60.00
5	TO CHECK WIRING & ELECTRICAL SYSTEM & ETC	New	120.00	15.00
	Gross Labour	r Cost (S\$)	840.00	545.00
	Report was unsubmitted during this	print-out.		

< END OF ESTIMATES >