

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22005396/UVY3N2**Date:** 14/06/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00022912201

Claimant Vehicle No : SFM1228P **Insured Vehicle No :** GBH1860L

Date of Loss: 03/06/2022 Nature of Claim: TP Claim No: SNM22D203932/C02/TANKW

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SFM1228P**

Make & Model: MAZDA 3, 1.5 4DR M-HYBRID ELEGANCE (A) Engine No: P520727395

Reg. Date: 13/04/2021 (Man. Year: 2021) Chassis No: JM6BP2SAAM1107125

Colour: Blue Odometer: 30952 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/45R18 Rear Tyre Size: 215/45R18

Front Left Side: Bridgestone 7 mm Rear Left Side: Bridgestone 7 mm

Front Right Side: Bridgestone 7 mm Rear Right Side: Bridgestone 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,156.02	2,444.48	5,711.54	70.03
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,350.00	1,580.00	1,770.00	52.84
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	11,506.02	4,024.48	7,481.54	65.02
Approved Total (Overridden) (\$\$)		3,200.00		
Nett Amount (\$\$)	11,506.02	3,200.00	8,306.02	72.19

INSPECTION

Date of Assignment: 07/06/2022

Date Inspected: 07/06/2022 Inspected At: Nineteen Autowerks Pte Ltd - Woodlands (HQ)
39 Woodlands Close, MEGA@Woodlands #01-24
Singapore 737856

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 14 Jun 2022)

Parts: 143 MAZDA 3 1.5 4DR M-HYBRID ELEGANCE (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SFM1228P)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOTLID	Repair	1,093.80 FL	*- FL
2	2		*REAR BOOT LAMPS	Not Necessary	1,166.00 FL	*- FL
3	1		*REAR BOOT INNER LOCK	Not Necessary	186.50 FL	*- FL
4	1		*REAR BOOT RUBBER	Twisted	178.60 FL	*178.60 FL
5	1		*REAR BOOT LOGO	Not Necessary	99.00 FL	*- FL
6	1		*REAR BOOT MAZDA 3 EMBLEM	Necessary	98.00 FL	*68.00 FL
7	1		*REAR BOOT SKYACTIVE EMBLEM	Necessary	48.00 FL	*48.00 FL
8	2		*REAR TAILLAMPS	Not Necessary	1,374.00 FL	*- FL
9	1		*REAR END PANEL	Dented/Bent	580.00 FL	*580.00 FL
10	1		*REAR END PANEL TOP GARNISH	Twisted	249.00 FL	*249.00 FL
11	1		*REAR SMART KEYLESS SENSOR	Not Necessary	395.00 FL	*- FL
12	1		*REAR BUMPER	Distorted	986.00 FL	*986.00 FL
13	1		*REAR BUMPER INNER SPONGE	Not fitted	205.50 FL	*- FL
14	2		*REAR BUMPER REFLECTORS	Not Necessary	174.40 FL	*- FL
15	1		*REAR BUMPER REINFORCEMENT	Bent	385.00 FL	*385.00 FL
16	2		*REAR BUMPER SIDE RETAINERS	Necessary	136.00 FL	*136.00 FL
17	2		*REAR BUMPER BRACKETS	No such part	96.00 FL	*- FL
18	1		*REAR DIFFUSER	Not fitted	380.90 FL	*- FL
19	1		*REAR DIFFUSER GARNISH	Not Necessary	186.10 FL	*- FL
20	1		*SUNDRIES	Not Necessary	60.00 FS	*- FS
21	1		*SET REAR BUMPER CLIPS	Necessary	100.00 FS	*50.00 FS
22	1		*SET REAR END PANEL TOP GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
23	1		*REAR END PANEL SEALANT	Necessary	80.00 FS	*50.00 FS
24	1		*REVERSE SENSOR WITH MODULE	Shorted	300.00 FS	*200.00 FS
25	1		*REAR LICENCE PLATE	Scratched	350.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,957.80	2,970.60
- List Item Discount on L Items 10.00/20.00% (\$\$)	801.78	526.12
Total Parts (\$\$)	8,156.02	2,444.48

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,500.00	600.00
2	SPRAY PAINTING	New	1,300.00	880.00
3	CHECK WIRING SYSTEM AFTER DISCONNECT & CONNECT	New	80.00	20.00
4	TRANSFER BOOTLID MECHANISM AND WIRING ASSEMBLY	New	120.00	0.00
5	REMOVE & REFIT REVERSE SENSOR AND CAMERA	New	250.00	50.00
6	TO APPLY UNDERCOATING FOR RUST ROOFING	New	100.00	30.00
Gross Labour Cost (\$\$)			3,350.00	1,580.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >