



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. YQ 6495E

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|------------------------------------|--|----------------------|---------------------------|-------------------|
| <u>REPLACEMENT OF PARTS</u> | | | | |
| 1 | FRONT GRILLE | SERVICEABLE | 1,250.00 | - |
| 1 | FRONT PANEL | TO REPAIR SEE LABOUR | 2,459.02 | - |
| 1 | FRONT PANEL 'FUSO' EMBLEM | NOT NECESSARY | 128.00 | - |
| 1 | FRONT BUMPER | TO REPAIR SEE LABOUR | 1,350.00 | - |
| 1 | O/S FRONT BUMPER BRACKET | TO REPAIR SEE LABOUR | 187.50 | - |
| 1 | O/S FRONT BUMPER SIDE GARNISH | SERVICEABLE | 340.62 | - |
| 1 | O/S HEAD LAMP | CUT | 554.65 | 554.65 |
| 1 | O/S SIGNAL LAMP | SERVICEABLE | 294.64 | - |
| 1 | O/S SIDE LAMP | SERVICEABLE | 186.41 | - |
| 1 | O/S SIDE PANEL | CRACKED | 505.14 | 505.14 |
| 1 | O/S SIDE MIRROR | CRACKED | 107.67 | 107.67 |
| 1 | O/S SIDE MIRROR BRACKET | BENT | 454.00 | 422.00 |
| 1 | FRONT WINDSCREEN GLASS | CRACKED | 1,338.08 | 1,338.08 |
| 1 | FRONT WINDSCREEN GLASS RUBBER | CUT | 492.05 | 356.45 |
| 1 | FRONT WIPER MOTOR | SERVICEABLE | 734.15 | - |
| 1 | FRONT WIPER LINK | SERVICEABLE | 523.00 | - |
| 1 | FRONT WIPER GARNISH | SERVICEABLE | 382.72 | - |
| 1 | O/S WIPER ARM | BENT | 287.00 | 112.35 |
| 1 | DASHBOARD | SERVICEABLE | 877.00 | - |
| | LESS 10% DISCOUNT | | -1,245.16 | - |
| | LESS 25% DISCOUNT | | - | -849.08 |
| | | | 11,206.49 | 2,547.26 |
| <u>SPECIAL NETT ITEMS</u> | | | | |
| 1 | FRONT WINDSCREEN 'IU' BRACKET (SN) | NECESSARY | 80.00 | 26.00 |
| | | | 80.00 | 26.00 |
| <u>LABOUR</u> | | | | |
| | LABOUR CHARGES. INCLUSIVE OF THE REPAIR OF FRONT PANEL, FRONT BUMPER AND O/S FRONT BUMPER BRACKET. | | 2,500.00 | 300.00 |

Report Ref No. CS/SMO22005405/Kqy3m4



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|------------------------------------|--|---------------|---------------------------|-------------------|
| | TO PUTTY AND SPRAY PAINTING. | | 1,200.00 | 500.00 |
| | TO CHECK,REPLACE,REPAIR WIRING. | | 120.00 | 20.00 |
| | REMOVE AND REFIX IN-CAR CAMERA. | NOT NECESSARY | 160.00 | - |
| | REMOVE AND REFIX FRONT WINDSCREEN GLASS. | | 250.00 | 120.00 |
| | REMOVE AND REFIX FRONT DASHBOARD. | NOT NECESSARY | 380.00 | - |
| | TO RE-SEAL ANTI RUST. | NOT NECESSARY | 160.00 | - |
| | | | 4,770.00 | 940.00 |
| GRAND TOTAL | | | 16,056.49 | 3,513.26 |
| RECOMMENDED COST OF REPAIRS | | | | 3,513.26 |

Report Ref No. CS/SMO22005405/Kqy3m4

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.